<b>PCN Number:</b> 20170104005				<b>PCN Date:</b> Jan. 12, 2017				
	for TPS546C23				-			
Customer Contact					Г	ept:	Quality Services	
Change Type:	<u>I Cit manage</u>	<u>-</u>				СРС	Quality Services	
Assembly Site			Design			l W	afer Bump Site	
Assembly Proce	SS		Data She	et .			afer Bump Material	
Assembly Materials			Part number change				afer Bump Process	
Mechanical Specification		İΠ	Test Site			_	afer Fab Site	
Packing/Shipping/Labeling		İΠ	Test Process				afer Fab Materials	
			<u>=</u>		Ī	W	afer Fab Process	
Notification Details								
Description of Change:								
Texas Instruments Incorporated is announcing an information only notification.								
The product datasheet(s) is being updated as summarized below. The following change history provides further details.								
l inc ronoving chang	o motor, provi	400	· ar circir ac					
TEXAS							TPS546C23	
Instruments				SLUS	SCC7B -	-JULY 201	6-REVISED NOVEMBER 2016	
Changes from Revision A (August 2016) to Revision B								
<ul> <li>Changed Simplified Application schematic – showing the ADDR0 and ADDR1 pins</li></ul>								
_								
Deleted "FB" from the Input voltage VSEL, SS row of the Absolute Maximum Ratings table, and added "FB" to the SYNC, RESET/PGD row								
Added M <sub>IOUT(acc)</sub> spec for ambient temp								
			nnections					
Deleted "Read only " from the Default Behavior column of Table 4 for CMD Codes 78h through 80h								
Society Floridate Delicate Delicate Column of Fable 4 for OND Godes For allough continues 55								
The datasheet numb	er will be chan	gino	<b>a</b> .					
Device Family			Change From:				Change To:	
TPS546C23			SLUSCC7A				SLUSCC7B	
These changes may be reviewed at the datasheet links provided. http://www.ti.com/product/TPS546C23								
Reason for Change:								
To accurately reflect	device therma	al ch	<u>aract</u> eristi	cs.				
Anticipated impac	t on Fit, Form	ı, Fı	ınction, (	uality or Rel	iabil	ity (p	ositive / negative):	
No anticipated impact. This is a specification change announcement only. There are no changes								
to the actual device.								
Changes to product identification resulting from this PCN:								
None.								
Product Affected:								
TPS546C23RVFR	TPS546C23I	RVFT	-					

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com