PCN Number:	20171030000				2, 201	7
		ADC12J2700, AD	C12J400			T
Customer Contact:	PCN Manager			De	pt:	Quality Services
Change Type:					ı	
Assembly Site		Design		Щ		Bump Site
Assembly Process	X	Data Sheet		Щ		Bump Material
Assembly Materials		Part number cha	nge	H		Bump Process
Mechanical Specific		Test Site		H		Fab Site
Packing/Shipping/I	Labeling	Test Process		H		Fab Materials Fab Process
	Na	tification De	taile		warei	rab Process
Description of Chang		diffication be	Lalis			
Texas Instruments Inco The product datasheet(The following change h	orporated is ann (s) is being upda	ited as summariz			tificatio	on.
TEXAS INSTRUMENTS					ADC	12J1600, ADC12J2700
			SLAS	969D – .	JANUARY 2	014-REVISED OCTOBER 2017
Changes from Revision C	(July 2015) to Revis	ion D				Page
Changed reset value of a	address 0x006 from (0x03 to 0x13 in Memory	Map table.			57
 Changed reset value of address 0x006 from 0x03 to 0x13 in Standard SPI-3.0 Registers table						
version Register section						01
TEXAS INSTRUMENTS Changes from Revision C.	(July 2015) to Ravis	on D	SL	AS989D	-JANUARY	ADC12J4000
INSTRUMENTS Changes from Revision C (*Austine 6/86 (8/15/85) /6/86/87 (9/15/85)				/ 2014-REVISED OCTOBER 2017
Changes from Revision C (Changed reset value of a	address 0x006 from 0	x03 to 0x13 in Memory	Map table.			Page
Changes from Revision C (Changed reset value of a Changed reset value of a	address 0x006 from 0	x03 to 0x13 in <i>Memory</i> x03 to 0x13 in <i>Standar</i>	Map table.	egiste	rs table	Page
Changes from Revision C (Changed reset value of a Changed reset value of a Changed 0x03 to 0x13 in	address 0x006 from 0 address 0x006 from 0 a reset value and des	x03 to 0x13 in <i>Memory</i> x03 to 0x13 in <i>Standar</i>	Map table.	egiste	rs table	Page
Changes from Revision C (Changed reset value of a Changed reset value of a	address 0x006 from 0 address 0x006 from 0 a reset value and des	x03 to 0x13 in <i>Memory</i> x03 to 0x13 in <i>Standar</i>	Map table.	egiste	rs table	Page
Changes from Revision C (Changed reset value of a Changed reset value of a Changed 0x03 to 0x13 in	address 0x006 from 0 address 0x006 from 0 reset value and des	x03 to 0x13 in <i>Memory</i> x03 to 0x13 in <i>Standar</i> cription of bits 7-0 and	Map table.	egiste	rs table	Page
Changes from Revision C (Changed reset value of a Changed reset value of a Changed 0x03 to 0x13 in Version Register section.	address 0x006 from 0 address 0x006 from 0 reset value and des	x03 to 0x13 in <i>Memory</i> x03 to 0x13 in <i>Standar</i> cription of bits 7-0 and	Map table.	egistei 00 001	rs table	Page 53 56 1 0011 in <i>Chip</i> 57
Changes from Revision C (Changed reset value of a Changed reset value of a Changed 0x03 to 0x13 in Version Register section. The datasheet number	address 0x006 from 0 address 0x006 from 0 a reset value and des will be changing	x03 to 0x13 in <i>Memory</i> x03 to 0x13 in <i>Standar</i> cription of bits 7-0 and	Map table.	egistei 00 001	rs table	Page
Changes from Revision C (Changed reset value of a Changed reset value of a Changed 0x03 to 0x13 in Version Register section. The datasheet number Device Family	address 0x006 from 0 address 0x006 from 0 a reset value and des will be changing	x03 to 0x13 in Memory x03 to 0x13 in Standar cription of bits 7-0 and 	Map table.	egister 00 001	rs table	Page
Changes from Revision C (Changed reset value of a Changed reset value of a Changed 0x03 to 0x13 in Version Register section. The datasheet number Device Family ADC12J1600, ADC12	address 0x006 from 0 address 0x006 from 0 arcset value and desuming will be changing	x03 to 0x13 in Memory x03 to 0x13 in Standar cription of bits 7-0 and Change From: SLAS969C SLAS989C	Map table. rd SPI-3.0 R changed 00	egister 00 001	Change	Page
Changes from Revision C (Changed reset value of a Changed reset value of a Changed 0x03 to 0x13 in Version Register section. The datasheet number Device Family ADC12J1600, ADC12: ADC12J4000	address 0x006 from 0 address 0x006 from 0 address 0x006 from 0 areset value and described will be changing 02700 reviewed at the	construction of bits 7-0 and cription of bits	Map table. rd SPI-3.0 R changed 00	egister 00 001	Change	Page
Changes from Revision C (Changed reset value of a Changed reset value of a Changed 0x03 to 0x13 in Version Register section. The datasheet number Device Family ADC12J1600, ADC12 ADC12J4000 These changes may be	address 0x006 from 0 address 0x006 from 0 address 0x006 from 0 areset value and described by the changing 12700 reviewed at the duct/ADC12J160	constant of the constant of th	Map table. rd SPI-3.0 R changed 00	egister 00 001	Change	Page
Changes from Revision C (Changed reset value of a Changed reset value of a Changed 0x03 to 0x13 in Version Register section. The datasheet number Device Family ADC12J1600, ADC12: ADC12J4000 These changes may be http://www.ti.com/proc	address 0x006 from 0 address 0x006 from 0 address 0x006 from 0 areset value and described by the changing 12700 reviewed at the duct/ADC12J160	constant of the constant of th	Map table. rd SPI-3.0 R changed 00	egister 00 001	Change	Page
Changes from Revision C (Changed reset value of a Changed reset value of a Changed 0x03 to 0x13 in Version Register section. The datasheet number Device Family ADC12J1600, ADC12 ADC12J4000 These changes may be http://www.ti.com/prochttp://www.ti.com/proch	will be changing J2700 reviewed at the duct/ADC12J400	construction of bits 7-0 and cription of bits	Map table. d SPI-3.0 R changed 00	degister 00 001	Change SLAS9	Page
Changes from Revision C (Changed reset value of a Changed reset value of a Changed 0x03 to 0x13 in Version Register section. The datasheet number Device Family ADC12J1600, ADC12 ADC12J4000 These changes may be http://www.ti.com/procenty-//	address 0x006 from 0 address 0x006 from 0 address 0x006 from 0 areset value and desa will be changing J2700 reviewed at the duct/ADC12J400 and descriptions and	x03 to 0x13 in Memory x03 to 0x13 in Standar cription of bits 7-0 and Change From: SLAS969C SLAS989C datasheet links p	Map table. Id SPI-3.0 R changed 00	the f	Change SLAS9 SLAS9	Page
Changes from Revision C (Changed reset value of a Changed reset value of a Changed 0x03 to 0x13 in Version Register section. The datasheet number Device Family ADC12J1600, ADC12 ADC12J4000 These changes may be http://www.ti.com/procents.	address 0x006 from 0 address 0x006 from 0 address 0x006 from 0 areset value and descriptions are descriptions are not fit, Form, Fu	control of the interconne	or Relia	the f	Change SLAS9 SLAS9	Page
Changes from Revision C (Changed reset value of a Changed reset value of a Changed 0x03 to 0x13 in Version Register section. The datasheet number Device Family ADC12J1600, ADC12 ADC12J4000 These changes may be http://www.ti.com/proce http://www.ti.com/proce Reason for Change: To reflect the device pin Anticipated impact o No anticipated impact.	address 0x006 from 0 address 0x006 from 0 address 0x006 from 0 areset value and descriptions are reviewed at the duct/ADC12J400 an descriptions are retirements as a specific from the reviewed at the duct/ADC12J400 and the reviewed at the reviewed at the duct/ADC12J400 and the reviewed at the reviewed	cription of bits 7-0 and Change From: SLAS969C SLAS989C datasheet links pool	orovided.	the f	Change SLAS9 SLAS9	Page

Product Affected:			
ADC12J1600NKE	ADC12J1600NKER	ADC12J1600NKET	ADC12J2700NKE
ADC12J2700NKER	ADC12J2700NKET	ADC12J4000NKE	ADC12J4000NKER
ADC12J4000NKET			

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com