

PCN-CCX-001749

Product Change Notice

Change Type:

Issue Date: January 24, 2020

Add Assembly Production Site – ASE Taiwan

Parts Affected:

BCM53101MIMLG BCM53101MIMLGG BCM53101PIMLG BCM53101EIMLG BCM53101MKMLG BCM53101PKMLG BCM53101EKMLG

Description and Extent of Change:

Add ASE Taiwan as the assembly supplier for the above devices

Reasons for Change:

Current assembly factory (StatsChipPAC Singapore) is discontinuing the ASSEMBLY ARRAY and PLASTIC LEADED manufacturing operation

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There will be no change in fit, form, function, quality or reliability

Effective Date of Change:

May 31, 2020



Qualification Data:

Package Qualification Reference#:	3655.0001, 3655.0002, 3655.0003
Fab Technology:	40nm
Package Type:	DR-QFN
Package Size:	12x12mm
Lead Count:	148
Wire Bond Composition	Cu_PD_Au
Mold Compound	EME-G6321SB

Stress Test	Condition	Read points	Lot ID	Sample Size	Requirements	Results
		Cycles / Hrs.				(# fail/ss)
Precondition	MSL3 JESD22-A113E		Lot#1	130 units	0 failures	0 / 130
			Lot#2	130 units	0 failures	0 / 130
			Lot#3	130 units	0 failures	0 / 130
Temp Cycle	-55°C / 125°C JEDEC Std. 22-A104-C Cond. B	1000 cycles	Lot#1	30 units	0 failures	0 / 30
			Lot#2	30 units	0 failures	0 / 30
			Lot#3	30 units	0 failures	0 / 30
uHast	130°C/85%RH JEDEC Std. 22-A102-C	192hrs	Lot#1	30 units	0 failures	0 / 30
			Lot#2	30 units	0 failures	0 / 30
			Lot#3	30 units	0 failures	0 / 30
HTSL	TA=150°C	1000hrs	Lot#1	30 units	0 failures	0 / 30
			Lot#2	30 units	0 failures	0 / 30
			Lot#3	30 units	0 failures	0 / 30

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.