Product Discontinuation

PD_278_20

- ■ Last Order Date: 2021-04-15
- ■ Last Delivery Date: 2021-10-15

Reason: Product portfolio rationalization

DISCONTINUED				NEW (REPLACEMENT)			
Sales Name	SP Number	OPN	Package	Sales Name	SP Number	OPN	Package
IFX1763LD V	SP000937458	IFX1763LDVXUMA1	PG-TSON-10	TLS205B0LDV	SP001304002	TLS205B0LDVXUMA1	PG-TSON-10
IFX1763LD V33	SP000938782	IFX1763LDV33XUMA1	PG-TSON-10	TLS205B0LD V33	SP001303998	TLS205B0LDV33XUMA1	PG-TSON-10
IFX1763XEJ V	SP000938788	IFX1763XEJVXUMA1	PG-DSO-8	TLS205B0EJV	SP001136828	TLS205B0EJVXUMA1	PG-DSO-8
IFX1763XEJ V33	SP000938790	IFX1763XEJV33XUMA1	PG-DSO-8	TLS205B0EJ V33	SP001195396	TLS205B0EJV33XUMA1	PG-DSO-8
IFX1763XEJ V50	SP000938802	IFX1763XEJV50XUMA1	PG-DSO-8	TLS205B0EJ V50	SP001209408	TLS205B0EJV50XUMA1	PG-DSO-8
IFX54441EJ V	SP000953854	IFX54441EJVXUMA1	PG-DSO-8	TLS205B0EJV	SP001136828	TLS205B0EJVXUMA1	PG-DSO-8

Product Discontinuation

![Infineon logo]

PD_278_20

- Last Order Date: 2021-04-15
- Last Delivery Date: 2021-10-15

DISCONTINUED				NEW (REPLACEMENT)			
Sales Name	SP Number	OPN	Package	Sales Name	SP Number	OPN	Package
IFX54441EJ V33	SP000953844	IFX54441EJV33XUMA1	PG-DSO-8	TLS205B0EJ V33	SP001195396	TLS205B0EJV33XUMA1	PG-DSO-8
IFX54441EJ V50	SP000953834	IFX54441EJV50XUMA1	PG-DSO-8	TLS205B0EJ V50	SP001209408	TLS205B0EJV50XUMA1	PG-DSO-8
IFX54441LD V	SP000953892	IFX54441LDVXUMA1	PG-TSON-10	TLS205B0LDV	SP001304002	TLS205B0LDVXUMA1	PG-TSON-10
IFX54441LD V33	SP000953874	IFX54441LDV33XUMA1	PG-TSON-10	TLS205B0LD V33	SP001303998	TLS205B0LDV33XUMA1	PG-TSON-10

If you have any questions, please do not hesitate to contact your local sales office.