



## PRODUCT DISCONTINUATION NOTICE

**PDN No.: USA 2014-007**

<b>IXYS PRODUCT TYPE:</b>	<b>TYPE:</b>	<b>RECOMMEND REPLACEMENT:</b>
IXFT12N100Q	N CHANNEL -MOSFET	NO RECOMMENDED REPLACEMENT

REASON FOR DISCONTINUATION: **IMPROPER REFLOW CHARACTERISTICS IS CAUSING FAILURES**

LAST TIME ORDER DATE: **NO LAST TIME ORDER DATE**

LAST TIME DELIVERY DATE: **N/A**

INTERNAL REFERENCE:

In case of any question, please contact: Sudhir Kommineni s.kommineni@ixys.net

INITIATOR	TITLE/FUNCTION	DATE	E-MAIL
GORDON ROSETE	DEPT. HEAD QA	DEC. 12, 2014	G.ROSETE@IXYS.NET

### CUSTOMER RESPONSE:

(PLEASE FILL IN AND RETURN BY E-MAIL, FAX OR MAIL WITHIN 4 WEEKS)

<input type="checkbox"/>	for further questions/ information	Company:	_____
	please comment	Name & Position	_____
		Phone / Fax No:	_____

COMMENTS: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_