

QUALITY ALERT: PRODUCT RECALL QAlert-000114 Date: 8/12/2019

P1/2

| I IXI Semiern Lorboration ZULLEIVan Road Cama | | | | |
|--|---|--|--|--|
| | Semtech Corporation, 200 Flynn Road, Camarillo CA 93012 | | | |
| | Semtech Canada Corporation, 4281 Harvester Road, Burlington, Ontario L7L 5M4 Canada | | | |
| Semtech Irvine, 5141 California Ave., Suite 100, Irvine CA 92617 | | | | |
| Semtech Neuchatel Sarl, Route des Gouttes d'Or 40, CH-2000 Neuchatel Switzerland | | | | |
| Semtech Bristol - EMEA Limited, Block B, St James Court, Great Park Road, Bristol BS32 4QJ, UK | | | | |
| Semtech Corpus Christi SA de CV, Carretera Matamorros Edificio 7, Reynosa, Tamaulipas, Mexico 88780 | | | | |
| Semtech Plano, 1101 Resource Drive, Suite 121, Plano TX 75074 | | | | |
| | | | | |
| Recall Details | | | | |
| Recall Notification: | | | | |
| | | | | |
| discrepant product and instructs you to contain all material subject to this alert. You should immediately contain any unused product. | | | | |
| immediately contain any unused product. | - | | | |
| | Customer Part Number(s) Affected: X/A | | | |
| immediately contain any unused product. Part Number(s) Affected: • SC174MLTRT | Customer Part Number(s) Affected: N/A | | | |
| immediately contain any unused product. Part Number(s) Affected: SC174MLTRT Lot Number(s): | - | | | |
| immediately contain any unused product. Part Number(s) Affected: SC174MLTRT Lot Number(s): 168243 | Customer Part Number(s) Affected: N/A | | | |
| immediately contain any unused product. Part Number(s) Affected: SC174MLTRT Lot Number(s): 168243 FAB D0095800 | Customer Part Number(s) Affected: N/A Customer PO Reference N/A | | | |
| immediately contain any unused product. Part Number(s) Affected: SC174MLTRT Lot Number(s): 168243 | Customer Part Number(s) Affected: N/A Customer PO Reference N/A | | | |
| immediately contain any unused product. Part Number(s) Affected: SC174MLTRT Lot Number(s): 168243 FAB D0095800 | Customer Part Number(s) Affected: N/A Customer PO Reference N/A | | | |
| immediately contain any unused product. Part Number(s) Affected: SC174MLTRT Lot Number(s): 168243 FAB D0095800 Date Code: Quantity: ⊠ N/ | Customer Part Number(s) Affected: N/A Customer PO Reference N/A | | | |

Recall Description:

- Problem / Issue: Semtech Corporation is requesting the return of any and all unused SC174MLTRT for rescreen or replacement due to a customer reported failures at their board electrical test.
- Semtech's Quality team has isolated this issue to one of our assembly and test suppliers. A Supplier Corrective Action was initiated to follow up on root cause analysis and corrective actions.
- Semtech asks that the material identified above be returned to the addressed listed below • for immediate replacement.

| Case Reference | 52675 & 52691 🗌 N/A | FA Report Reference | FA-008797 | □ N/A |
|----------------|---------------------|---------------------|-------------|-------|
| RMA Reference | ⊠ N/A* | SCAR or CAPA Ref. | 2204 & 2206 | □ N/A |



QUALITY ALERT: PRODUCT RECALL QAlert-000114 Date: 8/12/2019

P2/2

| Instructions to Return Material | | | | |
|---|--|------------|--|--|
| * Please contact your Semtech sales representative for an RMA and reference this Quality Alert-000114. | | | | |
| Return material to: Carsem (M) S-Site Lot 52986.Taman Meru Ind Est Jelapang, Ipoh ,Perak, Malaysia 30720 Attention: Chen Wen Lee • | | | | |
| Issuing Authority | | | | |
| Semtech Business Unit: | Power Management | | | |
| Semtech Contact Info: | Pat Sanchez Semtech Corporation Sr. Manager, Corporate Quality 200 Flynn Road Camarillo, CA 93012 Psanchez@semtech.com Office: (805) 480-2074 Fax: (805) 498-3804 | FAA Street | | |

FOR FURTHER INFORMATION & WORLDWIDE SALES COVERAGE: http://www.semtech.com/contact/index.html#support