TAIYO YUDEN

Taiyo Yuden (U.S.A.), Inc. 10 N. Martingale Rd. Schaumburg, IL 60173 Tel (630) 237-2405 Fax (847) 240-1715 http://www.t-yuden.com

Notice of Discontinuation for TAIYO YUDEN (U.S.A.) Inc. Distributors

DATE: June 28th, 2019

RE: Discontinuation of Axial Leaded Ceramic Capacitors

REF NO.: UTY-DN19-06D

TAIYO YUDEN (U.S.A.) Inc. hereby gives notice that the following part numbers are to be discontinued **9/28/2019** for all TAIYO YUDEN (U.S.A) Inc. distributors. Please note that any last time buys must be made on or before **9/28/2019**. Orders for these components received after the issue date of this notice are Non-Cancelable and Non-Returnable.

Please reference *Appendix_UTY-DN19-06D_Part List* for complete list of discontinued parts and suggested alternatives.

*Please note the suggested alternative part numbers are not direct, drop-in replacements. Therefore, the part number spec/datasheet should be consulted for comparison details.

NOTE: The information in this notice is applicable only to TAIYO YUDEN (U.S.A.) Inc. distribution sales channels. Discontinuation and promotional status changes, change schedules, and availability may vary in other regions. Please contact the Taiyo Yuden sales office responsible for sales in your country for details on this notice.

Issued by TAIYO YUDEN (U.S.A.) INC. Sales Planning Department

| Discontinued Part | Suggested Alternative Part or Series | Notification Ref. No. | Notice Type | Date Issued L | TB Date Notes |
|-------------------|--------------------------------------|-----------------------|-----------------|---------------|--|
| EP025B103K-A-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B103K-B-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B105K-A-BZ | UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP025B105K-B-BZ | UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP025B105K-KFCZ | UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP025B105K-NACZ | UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP025B122K-A-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B122K-B-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B152K-B-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B182K-A-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B182K-B-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B222K-A-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B222K-B-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B224K-A-BZ | UMK107B7224KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP025B224K-B-BZ | UMK107B7224KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP025B272K-A-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B272K-B-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B332K-A-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B332K-B-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B392K-A-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B392K-B-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B472K-A-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B472K-B-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B474K-A-BZ | UMK107B7474KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP025B474K-B-BZ | UMK107B7474KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP025B562K-A-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B562K-B-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B682K-B-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP025B822K-B-BJ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| EP050B105K-A-BZ | UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP050B105K-B-BZ | UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP050B105K-NACZ | UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP050B106K-A-BZ | UMK325AB7106KM-P | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP050B106K-B-BZ | UMK325AB7106KM-P | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP050B106K-KFCZ | UMK325AB7106KM-P | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP050B106K-NACZ | UMK325AB7106KM-P | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP050B225K-A-BZ | UMK212BB7225KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP050B225K-B-BZ | UMK212BB7225KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP050B225K-NACZ | UMK212BB7225KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP050B475K-A-BZ | UMK316AB7475KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP050B475K-B-BZ | UMK316AB7475KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| EP050B475K-NACZ | UMK316AB7475KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| GP050B105K-A-BZ | UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| GP050B105K-B-BZ | UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| GP050B105K-NACZ | UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| GP050B474K-A-BZ | UMK107B7474KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| GP050B474K-B-BZ | UMK107B7474KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| GP075B225K-A-B | UMK212BB7225KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |

| | | | | | Diagon note alternative part is not a direct, drop in replacement |
|-----------------|------------------|--------------|-----------------|-----------|--|
| GP075B225K-B-B | UMK212BB7225KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | Please note alternative part is not a direct, drop-in replacement. 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| GP075B225K-KEC | UMK212BB7225KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| GP075B225K-NAC | UMK212BB7225KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| GP075B475K-A-B | UMK316AB7475KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| GP075B475K-B-B | UMK316AB7475KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| GP075B475K-KEC | UMK316AB7475KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| GP075B475K-NAC | UMK316AB7475KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B104K-A-B | HMK107B7104KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B104K-B-B | НМК107В7104КА-Т | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B105K-A-B | HMK316B7105KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B105K-B-B | HMK316B7105KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B154K-A-B | HMK316B7154KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B154K-B-B | HMK316B7154KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B224K-A-B | HMK212B7224KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B224K-B-B | HMK212B7224KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B334K-A-B | HMK316B7334KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B334K-B-B | HMK316B7334KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B473K-A-B | HMK107B7473KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B473K-B-B | HMK107B7473KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B474K-A-B | HMK316B7474KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| HP075B474K-B-B | HMK316B7474KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| JP050B106K-A-BZ | UMK325AB7106KM-P | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| JP050B106K-B-BZ | UMK325AB7106KM-P | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| JP050B106K-NACZ | UMK325AB7106KM-P | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B103K-A-B | QMK212B7103KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B103K-B-B | QMK212B7103KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B104K-A-B | QMK316B7104KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B104K-B-B | QMK316B7104KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B153K-A-B | QMK212B7153KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B153K-B-B | QMK212B7153KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B223K-A-B | QMK212B7223KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B223K-B-B | QMK212B7223KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B333K-A-B | QMK316B7333KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B333K-B-B | QMK316B7333KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B473K-A-B | QMK316B7473KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B473K-B-B | QMK316B7473KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B683K-A-B | QMK316B7683KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| QP075B683K-B-B | QMK316B7683KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B102K-A-B | SMK316B7102KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B102K-B-B | SMK316B7102KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B103K-A-B | SMK316B7103KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B103K-B-B | SMK316B7103KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B152K-A-B | SMK316B7152KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B152K-B-B | SMK316B7152KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B153K-A-B | SMK316B7153KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B153K-B-B | SMK316B7153KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B222K-A-B | SMK316B7222KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B222K-B-B | SMK316B7222KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | | | | | |

| SP075B223K-A-B | SMK316B7223KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
|------------------|------------------|--------------|-----------------|-----------|--|
| SP075B223K-B-B | SMK316B7223KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B332K-A-B | SMK316B7332KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B332K-B-B | SMK316B7332KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B472K-A-B | SMK316B7472KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B472K-B-B | SMK316B7472KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B682K-A-B | SMK316B7682KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| SP075B682K-B-B | SMK316B7682KF-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| TP025B104K-A-BZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| TP050B104K-A-B | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| TP050B104K-A-BZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| TP050B104K-A-BGZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| TP050B104K-B-B | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| TP050B104K-B-BZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| TP050B104K-B-BGZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| TP050B475K-A-BZ | UMK316AB7475KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| TP050B475K-B-BZ | UMK316AB7475KL-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| TP075B106K-A-B | UMK325AB7106KM-P | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| TP075B106K-B-B | UMK325AB7106KM-P | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| TP075B106K-KEC | UMK325AB7106KM-P | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| TP075B106K-NAC | UMK325AB7106KM-P | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B101K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B101K-A-BSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B101K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B101K-B-BSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B101K-KFCZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B101K-KFCHZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B101K-NACZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B101K-NACSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B102K-A-BJ | UMK105B7102KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B102K-A-BZ | UMK105B7102KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B102K-A-BSZ | UMK105B7102KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B102K-B-BZ | UMK105B7102KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B102K-B-BSZ | UMK105B7102KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B102K-KFCZ | UMK105B7102KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B102K-NACZ | UMK105B7102KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B102K-NACHZ | UMK105B7102KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B102K-NACSZ | UMK105B7102KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B103K-A-BZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B103K-A-BLZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B103K-A-BSZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B103K-B-BZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B103K-B-BSZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B103K-KFCZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B103K-KFCSZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B103K-NACZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | |
| UP025B103K-NACSZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B103K-NAC32 | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | |
| UP025B104K-A-BLZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | | | | 5/20/2013 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | | | | | |

| UP025B104K-A-BSZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
|------------------|------------------|--------------|-----------------|-----------|--|
| UP025B104K-B-BZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B104K-B-BSZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B104K-KFCZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B104K-KFCSZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B104K-NACZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B104K-NACSZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B121K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B121K-A-BSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B121K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B121K-KFCZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B121K-NACZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B121K-NACSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B123K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B123K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B151K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B151K-A-BSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B151K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B151K-KFCZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B151K-NACZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B151K-NACHZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B151K-NACSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B152K-A-BZ | UMK105B7152KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B152K-A-BSZ | UMK105B7152KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B152K-B-BZ | UMK105B7152KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B152K-KFCZ | UMK105B7152KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B152K-NACZ | UMK105B7152KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B152K-NACSZ | UMK105B7152KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B181K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B181K-A-BSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B181K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B181K-KFCZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B181K-NACSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B182K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B182K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B182M-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B183K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B183K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B221K-A-BZ | UMK105B7221KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B221K-A-BSZ | UMK105B7221KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B221K-B-BZ | UMK105B7221KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B221K-B-BSZ | UMK105B7221KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B221K-KFCZ | UMK105B7221KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B221K-NACZ | UMK105B7221KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B221K-NACSZ | UMK105B7221KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B222K-A-BZ | UMK105B7222KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B222K-A-BLZ | UMK105B7222KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B222K-A-BSZ | UMK105B7222KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B222K-B-BZ | UMK105B7222KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | | | | | |

| UP025B222K-KFCZ | UMK105B7222KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
|------------------|------------------|--------------|-----------------|-----------|--|
| UP025B222K-KFCSZ | UMK105B7222KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B222K-NACZ | UMK105B7222KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B222K-NACSZ | UMK105B7222KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B223K-A-BZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B223K-A-BLZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B223K-A-BSZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B223K-B-BZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B223K-KFCZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B223K-KFCSZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B223K-NACZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B223K-NACSZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B271K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B271K-A-BSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B271K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B271K-B-BHZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B271K-KFCZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B271K-NACZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B271K-NACSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B272K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B272K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B273K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B273K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B331K-A-BZ | UMK105B7331KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B331K-A-BSZ | UMK105B7331KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B331K-B-BSZ | UMK105B7331KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B331K-KFCZ | UMK105B7331KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B331K-NACZ | UMK105B7331KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B331K-NACSZ | UMK105B7331KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B332K-A-BZ | UMK105B7332KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B332K-A-BLZ | UMK105B7332KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B332K-A-BSZ | UMK105B7332KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B332K-B-BZ | UMK105B7332KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B332K-KFCZ | UMK105B7332KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B332K-NACZ | UMK105B7332KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B332K-NACSZ | UMK105B7332KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B333K-A-BZ | HMK107B7333KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B333K-A-BLZ | HMK107B7333KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B333K-A-BSZ | HMK107B7333KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B333K-B-BZ | HMK107B7333KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B333K-KFCZ | HMK107B7333KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B333K-KFCSZ | HMK107B7333KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B333K-NACZ | HMK107B7333KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B333K-NACSZ | HMK107B7333KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B391K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B391K-A-BSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B391K-KFCZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B391K-NACZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B391K-NACSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| | | | | | |

| UP025B392K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
|------------------|------------------|--------------|-----------------|-----------|--|
| UP025B392K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B392K-NACZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B393K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B393K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B471K-A-BJ | UMK105B7471KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B471K-A-BZ | UMK105B7471KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B471K-A-BSZ | UMK105B7471KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B471K-B-BZ | UMK105B7471KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B471K-B-BHZ | UMK105B7471KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B471K-B-BSZ | UMK105B7471KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B471K-KFCZ | UMK105B7471KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B471K-NACZ | UMK105B7471KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B471K-NACHZ | UMK105B7471KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B471K-NACSZ | UMK105B7471KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B472K-A-BZ | UMK105B7472KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B472K-A-BLZ | UMK105B7472KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B472K-A-BSZ | UMK105B7472KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B472K-B-BZ | UMK105B7472KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B472K-KFCZ | UMK105B7472KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B472K-NACZ | UMK105B7472KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B472K-NACSZ | UMK105B7472KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B473K-A-BZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B473K-A-BLZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B473K-A-BSZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B473K-B-BZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B473K-KFCZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B473K-KFCHZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B473K-NACZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B473K-NACSZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B561K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B561K-A-BSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B561K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B561K-KFCZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B561K-NACZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B561K-NACSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B562K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B562K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B563K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B563K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B681K-A-BZ | UMK105B7681KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B681K-A-BSZ | UMK105B7681KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B681K-B-BZ | UMK105B7681KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B681K-B-BSZ | UMK105B7681KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B681K-KFCZ | UMK105B7681KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B681K-NACZ | UMK105B7681KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B681K-NACSZ | UMK105B7681KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B682K-A-BZ | UMK105B7682KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B682K-A-BLZ | UMK105B7682KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | | | | | |

| UP025B682K-A-BSZ | UMK105B7682KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
|------------------|------------------|--------------|-----------------|-----------|--|
| UP025B682K-B-BZ | UMK105B7682KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B682K-KFCZ | UMK105B7682KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B682K-NACZ | UMK105B7682KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B682K-NACSZ | UMK105B7682KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B683K-A-BZ | HMK212B7683KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B683K-A-BSZ | HMK212B7683KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B683K-B-BZ | HMK212B7683KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B683K-KFCZ | HMK212B7683KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B683K-NACZ | HMK212B7683KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B683K-NACSZ | HMK212B7683KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B821K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B821K-A-BSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B821K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B821K-KFCZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B821K-NACZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B821K-NACSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B822K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B822K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B823K-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025B823K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025F103Z-A-BZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F103Z-A-BLZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F103Z-A-BSZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F103Z-B-BZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F103Z-B-BHZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F103Z-KFCZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F103Z-NACZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F103Z-NACSZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F104Z-A-BZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F104Z-A-BLZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F104Z-A-BSZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F104Z-B-BZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F104Z-KFCZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F104Z-NACZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F104Z-NACSZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F223Z-A-BZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F223Z-A-BSZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F223Z-B-BZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F223Z-B-BSZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F223Z-NACZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F223Z-NACSZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F473Z-A-BZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F473Z-A-BLZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F473Z-A-BSZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F473Z-B-BZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025F473Z-NACSZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B5105K-A-BZ | UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025B5105K-B-BZ | UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | | | | | |

| | | | Discussion of the | 0/00/0040 | 0/00/0010 |
|-------------------|-----------------|--------------|-------------------|-----------|--|
| | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CK010CV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH010D-A-BSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CK010CV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH010D-NACZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH010D-NACSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CJ030CV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CJ030CV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH100DV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH100J-A-BSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH100DV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH100DV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH100J-NACSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH101JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH101JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH101J-A-BSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH101JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH101JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH101J-KFCSZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH101JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH101J-NACSZ | UMK105CH101JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH101K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| | UMK105CH102JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH102J-A-BSZ | UMK105CH102JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH102JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH102JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH102JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH102J-NACSZ | UMK105CH102JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH111J-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH111J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| | UMK105CH120JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH120J-A-BSZ | UMK105CH120JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH120JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH120J-NACSZ | UMK105CH120JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH121JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH121J-A-BLZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH121J-B-BZ | UMK105CH121JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH121JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH131J-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH131J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH150J-A-BZ | UMK105CH150JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH150J-A-BSZ | UMK105CH150JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | UMK105CH150JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH150J-KFCZ | UMK105CH150JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH150J-NACZ | UMK105CH150JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH150J-NACSZ | UMK105CH150JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH151J-A-BZ | UMK105CH151JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH151J-A-BLZ | UMK105CH151JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH151J-A-BSZ | UMK105CH151JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | | | | | |

| UP025CH151J-B-BZ UMK105CH151JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
|-----------------------------------|--------------|-----------------|-----------|--|
| UP025CH151J-B-BHZ UMK105CH151JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH151J-NACZ UMK105CH151JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH151J-NACHZ UMK105CH151JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH151J-NACSZ UMK105CH151JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH160J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH160J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH161J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH161J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH180J-A-BZ UMK105CH180JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH180J-A-BSZ UMK105CH180JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH180J-B-BZ UMK105CH180JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH180J-KFCZ UMK105CH180JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH180J-NACZ UMK105CH180JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH180J-NACSZ UMK105CH180JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH181J-A-BZ UMK105CH181JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH181J-B-BZ UMK105CH181JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH181J-NACZ UMK105CH181JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH1R2D-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH1R2D-A-BSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH1R2D-KFCZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH1R2D-NACZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH1R2D-NACSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH1R5D-A-BZ UMK105CK1R5CV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH1R5D-A-BSZ UMK105CK1R5CV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH1R5D-KFCZ UMK105CK1R5CV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH1R5D-NACZ UMK105CK1R5CV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH1R5D-NACSZ UMK105CK1R5CV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH1R8D-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH1R8D-A-BSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH1R8D-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH1R8D-KFCZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH1R8D-NACZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH1R8D-NACSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH200J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH200J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH200J-NACZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH201J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH201J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH220J-A-BZ UMK105CH220JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH220J-A-BSZ UMK105CH220JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH220J-B-BZ UMK105CH220JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH220J-NACZ UMK105CH220JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH220J-NACSZ UMK105CH220JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH221J-A-BZ UMK105CH221JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH221J-A-BLZ UMK105CH221JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH221J-A-BSZ UMK105CH221JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH221J-B-BZ UMK105CH221JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH221J-B-BHZ UMK105CH221JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | | Discontinuation | 0,20,2013 | or to the anemative part is not a direct, drop-in replacement. |

| UP025CH221J-B-BSZ UMK105CH221JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
|-----------------------------------|--------------|-----------------|-----------|--|
| UP025CH221J-KFCZ UMK105CH221JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH221J-NACZ UMK105CH221JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH221J-NACSZ UMK105CH221JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH240J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH240J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH241J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH241J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH270J-A-BZ UMK105CH270JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH270J-A-BSZ UMK105CH270JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH270J-B-BZ UMK105CH270JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH270J-KFCSZ UMK105CH270JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH270J-NACZ UMK105CH270JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH270J-NACSZ UMK105CH270JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH271J-A-BZ UMK105CH271JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH271J-B-BZ UMK105CH271JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH2R2D-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH2R2D-A-BSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH2R2D-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH2R2D-KFCZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH2R2D-NACZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH2R2D-NACSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH2R7D-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH2R7D-A-BSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH2R7D-KFCZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH2R7D-NACZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH2R7D-NACSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH300J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH300J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH301J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH301J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH330J-A-BZ UMK105CH330JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH330J-A-BLZ UMK105CH330JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH330J-A-BSZ UMK105CH330JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH330J-B-BZ UMK105CH330JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH330J-KFCZ UMK105CH330JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH330J-NACZ UMK105CH330JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH330J-NACSZ UMK105CH330JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH331J-A-BZ UMK105CH331JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH331J-A-BLZ UMK105CH331JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH331J-A-BSZ UMK105CH331JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH331J-B-BZ UMK105CH331JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH331J-KFCSZ UMK105CH331JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH331J-NACZ UMK105CH331JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH331J-NACSZ UMK105CH331JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH360J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH360J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH361J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| | | | 6/28/2019 | |
| UP025CH361J-B-BZ | UTY-DN19-06D | Discontinuation | 0/20/2019 | 9/28/2019 |

| UP025CH390J-A-BZ UMK105CH390JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
|-----------------------------------|--------------|-----------------|-----------|---|
| UP025CH390J-A-BSZ UMK105CH390JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH390J-B-BZ UMK105CH390JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH390J-NACZ UMK105CH390JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH390J-NACSZ UMK105CH390JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH391J-A-BZ UMK105CH391JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH391J-B-BZ UMK105CH391JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH3R3D-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH3R3D-A-BSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH3R3D-KFCZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH3R3D-NACZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH3R3D-NACSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH3R9D-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH3R9D-A-BSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH3R9D-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH3R9D-KFCZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH3R9D-NACZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH3R9D-NACSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH430J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH430J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH431J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH431J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH470J-A-BZ UMK105CH470JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH470J-A-BSZ UMK105CH470JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH470J-B-BZ UMK105CH470JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH470J-B-BSZ UMK105CH470JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH470J-KFCZ UMK105CH470JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH470J-NACZ UMK105CH470JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH470J-NACSZ_UMK105CH470JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH471J-A-BZ UMK105CH471JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH471J-A-BSZ UMK105CH471JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH471J-B-BZ UMK105CH471JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH471J-KFCZ UMK105CH471JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH471J-NACZ UMK105CH471JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | |
| UP025CH471J-NACSZ UMK105CH471JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH4R7D-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. 9/28/2019 |
| UP025CH4R7D-A-BSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH4R7D-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH4R7D-KFCZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH4R7D-NACZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH4R7D-NACSZ | | | 6/28/2019 | |
| | UTY-DN19-06D | Discontinuation | | 9/28/2019 |
| | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH511J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH560J-A-BZ UMK105CH560JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH560J-A-BLZ UMK105CH560JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH560J-A-BSZ UMK105CH560JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH560J-B-BZ UMK105CH560JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | | | | |

| UP025CH560J-NACZ UMK105CH560JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
|-----------------------------------|--------------|-----------------|------------------------|--|
| UP025CH560J-NACSZ UMK105CH560JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH561J-A-BZ UMK105CH561JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH561J-A-BLZ UMK105CH561JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH561J-B-BZ UMK105CH561JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH5R6K-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH5R6K-A-BSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH5R6K-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH5R6K-KFCZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH5R6K-NACZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH5R6K-NACSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH620J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH620J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH621J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH621J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH680J-A-BZ UMK105CH680JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH680J-A-BSZ UMK105CH680JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH680J-B-BZ UMK105CH680JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH680J-NACZ UMK105CH680JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH680J-NACSZ UMK105CH680JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH681J-A-BZ UMK105CH681JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH681J-A-BLZ UMK105CH681JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH681J-A-BSZ UMK105CH681JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH681J-B-BZ UMK105CH681JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH681J-NACZ UMK105CH681JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH681J-NACSZ UMK105CH681JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH6R8K-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH6R8K-A-BSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH6R8K-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH6R8K-KFCZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH6R8K-NACZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH6R8K-NACSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH750J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH750J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH751J-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH751J-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH820J-A-BZ UMK105CH820JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH820J-A-BHZ UMK105CH820JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH820J-A-BSZ UMK105CH820JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH820J-B-BZ UMK105CH820JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH820J-B-BHZ UMK105CH820JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH820J-NACZ UMK105CH820JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH820J-NACHZ UMK105CH820JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH820J-NACSZ UMK105CH820JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | |
| UP025CH821J-A-BZ UMK105CH821JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025CH821J-B-BZ UMK105CH821JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | |
| UP025CH8R2K-A-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. 9/28/2019 |
| UP025CH8R2K-A-BSZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH8R2K-B-BZ | UTY-DN19-06D | Discontinuation | 6/28/2019 6/28/2019 | 9/28/2019 |
| | | Discontinuation | 0/20/2019 | ジェクリアクトシ |

| UP025CH8R2K-KFCZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
|------------------|------------------|--------------|-----------------|-----------|--|
| UP025CH8R2K-NACZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH8R2K-NACS | Z | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH910J-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH910J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH911J-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025CH911J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL030D-B-BZ | UMK105CJ030CV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP025SL160J-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL160J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL200J-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL200J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL240J-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL240J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL300J-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL300J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL360J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL430J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL510J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL620J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL750J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP025SL750K-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050B103K-A-B | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B103K-A-BZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B103K-A-BGZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B103K-B-B | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B103K-B-BGZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B103K-KFC | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B103K-KFCGZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B103K-NAC | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B103K-NACGZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B104K-A-BZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B104K-A-BGZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B104K-B-BGZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B104K-KFCGZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B104K-NACGZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B153K-A-BZ | HMK107B7153KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B153K-A-BGZ | HMK107B7153KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B153K-B-BGZ | HMK107B7153KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B222K-A-BZ | UMK105B7222KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B222K-A-BGZ | UMK105B7222KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B222K-B-BGZ | UMK105B7222KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B222K-NACGZ | UMK105B7222KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B223K-A-BZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B223K-A-BGZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B223K-B-BGZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B223K-NACGZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B224K-A-BZ | UMK107B7224KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B224K-B-BZ | UMK107B7224KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | | | | | |

| UP050B224K-KFCZ | UMK107B7224KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
|------------------|------------------|--------------|-----------------|-----------|--|
| UP050B224K-NACZ | UMK107B7224KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B332K-A-BZ | UMK105B7332KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B332K-A-BGZ | UMK105B7332KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B332K-B-BGZ | UMK105B7332KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B332K-NACGZ | UMK105B7332KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B333K-A-BZ | HMK107B7333KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B333K-A-BGZ | HMK107B7333KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B333K-B-BGZ | HMK107B7333KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B472K-A-BZ | UMK105B7472KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B472K-A-BGZ | UMK105B7472KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B472K-B-BGZ | UMK105B7472KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B472K-KFCGZ | UMK105B7472KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B472K-NACGZ | UMK105B7472KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B473K-A-BZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B473K-A-BGZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B473K-B-BGZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B473K-NACGZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B474K-A-BZ | UMK107B7474KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B474K-B-BZ | UMK107B7474KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B474K-KFCZ | UMK107B7474KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B474K-NACZ | UMK107B7474KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B682K-A-BZ | UMK105B7682KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B682K-A-BGZ | UMK105B7682KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B682K-B-BGZ | UMK105B7682KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B683K-A-BZ | HMK212B7683KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B683K-A-BGZ | HMK212B7683KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050B683K-B-BGZ | HMK212B7683KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F103Z-A-BZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F103Z-A-BGZ | UMK105B7103KV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-A-B | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-A-BZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-A-BG | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-A-BGZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-A-BHZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-B-B | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-B-BFZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-B-BG | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-B-BGZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-B-BHZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-KFC | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-KFCG | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-KFCGZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-KFCHZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-NAC | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-NACG | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F104Z-NACGZ | UMK105B7104KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F223Z-A-B | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F223Z-A-BZ | UMK105B7223KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | | | | | |

| UP050F224Z-A-BZ | UMK107B7224KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
|-------------------|------------------|--------------|-----------------|-----------|--|
| UP050F224Z-A-BGZ | UMK107B7224KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F224Z-B-BGZ | UMK107B7224KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F224Z-NACGZ | UMK107B7224KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F333Z-A-BZ | HMK107B7333KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F473Z-A-B | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F473Z-A-BF | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F473Z-A-BZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F473Z-A-BGZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F473Z-A-BHZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F473Z-B-B | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F473Z-B-BGZ | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F473Z-KFC | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F473Z-NAC | UMK105B7473KV-FR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F474Z-A-BZ | UMK107B7474KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F474Z-A-BGZ | UMK107B7474KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050F474Z-B-BGZ | UMK107B7474KA-TR | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH101J-A-BZ | UMK105CH101JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH101J-A-BGZ | UMK105CH101JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH101J-B-BGZ | UMK105CH101JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH101J-NACGZ | UMK105CH101JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH102J-A-BZ | UMK105CH102JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH102J-A-BGZ | UMK105CH102JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH102J-B-BGZ | UMK105CH102JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH102J-KFCGZ | UMK105CH102JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH122J-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050CH122J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050CH122J-B-BGZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050CH151J-A-BZ | UMK105CH151JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH151J-A-BGZ | UMK105CH151JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH151J-B-BGZ | UMK105CH151JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH152J-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050CH152J-A-BGZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050CH152J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050CH152J-B-BGZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050CH182J-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050CH220J-A-BZ | UMK105CH220JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH220J-A-BGZ | UMK105CH220JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH220J-B-BGZ | UMK105CH220JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH221J-A-BZ | UMK105CH221JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH221J-A-BGZ | UMK105CH221JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH221J-B-BGZ | UMK105CH221JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH221J-NACGZ | UMK105CH221JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH222J-A-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050CH222J-A-BGZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050CH222J-B-BZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050CH222J-B-BGZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050CH222J-KFCZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| UP050CH222J-NACZ | | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
| | | | | | |

| UP050CH222J-NACGZ | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 |
|-----------------------------------|--------------|-----------------|-----------|--|
| UP050CH270J-A-BZ UMK105CH270JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH270J-A-BGZ UMK105CH270JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH270J-B-BGZ UMK105CH270JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH330J-A-BZ UMK105CH330JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH330J-A-BGZ UMK105CH330JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH330J-B-BGZ UMK105CH330JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH331J-A-BZ UMK105CH331JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH331J-A-BGZ UMK105CH331JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH331J-B-BGZ UMK105CH331JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH390J-A-BZ UMK105CH390JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH390J-A-BGZ UMK105CH390JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH390J-B-BGZ UMK105CH390JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH390J-KFCGZ UMK105CH390JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH470J-A-BZ UMK105CH470JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH470J-A-BGZ UMK105CH470JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH470J-B-BGZ UMK105CH470JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH471J-A-BZ UMK105CH471JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH471J-A-BGZ UMK105CH471JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH471J-B-BGZ UMK105CH471JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH471J-KFCGZ UMK105CH471JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH471J-NACGZ UMK105CH471JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH680J-A-BZ UMK105CH680JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH680J-A-BGZ UMK105CH680JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH680J-B-BGZ UMK105CH680JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH681J-A-BZ UMK105CH681JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH681J-A-BGZ UMK105CH681JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP050CH681J-B-BGZ UMK105CH681JV-F | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP075B105K-A-B UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP075B105K-B-B UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP075B105K-KEC UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP075B105K-NAC UMK107AB7105KA-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP075B5225K-A-B UMK212BB7225KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| UP075B5225K-B-B UMK212BB7225KG-T | UTY-DN19-06D | Discontinuation | 6/28/2019 | 9/28/2019 Please note alternative part is not a direct, drop-in replacement. |
| | | | | |