

## **Product Change Notification - SYST-30BGQX109**

Date:

05 Nov 2018

**Product Category:** 

**Ethernet Switches** 

**Affected CPNs:** 



#### **Notification subject:**

Data Sheet - KSZ8864CNX/RMNUB Integrated 4-Port 10/100 Mgd Switch with 2 MACs MII or RMII Int

#### **Notification text:**

SYST-30BGQX109

Microchip has released a new DeviceDoc for the KSZ8864CNX/RMNUB Integrated 4-Port 10/100 Mgd Switch with 2 MACs MII or RMII Int of devices. If you are using one of these devices please read the document located at <a href="KSZ8864CNX/RMNUB Integrated 4-Port 10/100 Mgd Switch with 2 MACs MII or RMII Int.">KSZ8864CNX/RMNUB Integrated 4-Port 10/100 Mgd Switch with 2 MACs MII or RMII Int.</a>

#### **Notification Status:**Final

## **Description of Change:**

1) Changed " The distance to fault is about  $0.4 \times {\text{Vct}_-}$  Fault [8-0]} " to " The distance to fault is about  $0.39 \times {\text{Vct}_-}$ 

{Vct\_Fault [8-0]}" in 3.1.9.3 " A LinkMD Example"

- 2) Changed " It's approximately 0.4m\*Vct\_- fault\_count[8:0]" to " It's approximately 0.39\*Vct\_- fault\_count[8:0]" and Changed bit [0] " Reserved" to " Vct\_fault\_count [8]"; changed " N/A Do not change" to " Bit [8] of Vct\_ fault\_count [8:0]" in TABLE 4-1: " Port Registers"
- 3) Changed Pin 41 "SM4RXD4" to "SM4RXD3"; edited Pin 21, 24, and 37 in FIGURE 2-1: 64-QFN Pin

Assignment (TOP View) onpage 6

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Manufacturability

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 05 Nov 2018

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

# Markings to Distinguish Revised from Unrevised Devices: N/A Attachment(s):

KSZ8864CNX/RMNUB Integrated 4-Port 10/100 Mgd Switch with 2 MACs MII or RMII Int

Please contact your local <u>Microchip sales office</u> with questions or concerns regarding this notification.

### **Terms and Conditions:**



If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our <u>PCN home page</u> select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the <u>PCN FAQ</u> section.

If you wish to <u>change your PCN profile</u>, <u>including opt out</u>, please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

## ${\it SYST-30BGQX109-Data\ Sheet-KSZ8864CNX/RMNUB\ Integrated\ 4-Port\ 10/100\ Mgd\ Switch\ with\ 2\ MACs\ MII\ or\ RMII\ Int}$

## Affected Catalog Part Numbers(CPN)

KSZ8864CNXC

KSZ8864CNXC-TR

KSZ8864CNXCA

KSZ8864CNXCA-TR

KSZ8864CNXI

KSZ8864CNXI-TR

KSZ8864CNXIA

KSZ8864CNXIA-TR

KSZ8864RMNUB

KSZ8864RMNUB-TR