



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M001001N

DATE: 01-Sep-2020

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1088CX-133+	N/A	27-Aug-2021	23-Feb-2022	Part can no longer be manufactured
Discontinuance	IC0410C778BF+LTB	N/A	27-Aug-2021	23-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX13050ESA+	N/A	27-Aug-2021	23-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX6175BASA/V+TCJX	MAX6175BASA/V+T	27-Aug-2021	23-Feb-2022	Part can no longer be manufactured
Discontinuance	VT1335SFC	N/A	27-Aug-2021	23-Feb-2022	Part can no longer be manufactured
Discontinuance	VT1335SFCX	N/A	27-Aug-2021	23-Feb-2022	Part can no longer be manufactured
Discontinuance	VT1336SFC	N/A	27-Aug-2021	23-Feb-2022	Part can no longer be manufactured
Discontinuance	VT1336SFCX	N/A	27-Aug-2021	23-Feb-2022	Part can no longer be manufactured
Discontinuance	VT1677SBFQX+CN8	VT1677SBFQX+CNQ	27-Aug-2021	23-Feb-2022	Part can no longer be manufactured
Discontinuance	VT297BFC-ADJ	N/A	27-Aug-2021	23-Feb-2022	Part can no longer be manufactured
Discontinuance	VT297BFCX-ADJ	N/A	27-Aug-2021	23-Feb-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Oct-2020