<b>PCN Number:</b> 20170921000	PCN Date:	Octo	ber 4, 2017		
Title: Datasheet for LM5170-Q1					
<b>Customer Contact:</b> PCN Manager		De	pt: Quality Services		
Change Type:			-		
	)esign	П	Wafer Bump Site		
	Pata Sheet	ΙĦ	Wafer Bump Material		
	art number change	lП	Wafer Bump Process		
	est Site	ΙĦ	Wafer Fab Site		
	est Process	Ħ	Wafer Fab Materials		
		ΙĦ	Wafer Fab Process		
Notification Details					
Description of Change:	meation Details				
Texas Instruments Incorporated is annou	uncing an information on	ly no	otification		
The product datasheet(s) is being update			Jenreacion:		
The following change history provides full					
The following change metery provides fall	tinei detailei				
<b>₹</b> ŢEXAS					
Instruments			LM5170-Q1		
	SN	/SAQ6/	A –NOVEMBER 2016–REVISED JUNE 2017		
Changes from Original (November 2016) to Revis	sion A		Pag		
Changed TQFP body size dimensions from: 6.00	0 mm v 6 00 mm to: 7 00 mm v	7 00 1	mm		
Changed Figure 26					
Changed Figure 40 and Figure 41					
Changed Figure 44					
Changed Equation 28			4		
Changed Equation 30			4		
Changed Equation 36			4		
Added text to Figure 53			4		
Changed Figure 55			4		
• Changed examples values for the $V_{LV\_max}$ , $V_{HV\_re}$					
Changed Equation 49					
Changed Equation 50					
Changed Equation 56      Changed Equation 59					
Changed Equation 59  Changed Equation 64 and Equation 65					
Changed Equation 64 and Equation 65     Changed Equation 75					
Changed Equation 76					
Changed Equation 77					
Changed Figure 75			6		
The datasheet number will be changing.					
Device Family	Change From:		Change To:		
·					
LM5170-Q1	snvsaq6		snvsaq6A		
These changes may be reviewed at the d	latasheet links provided.				
http://www.ti.com/product/LM5170-Q1					
Reason for Change:					
To accurately reflect device characteristics.					
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):					
No anticipated impact. This is a specifical	tion change announceme	ent o	only. There are no changes		
to the actual device.					

Changes to product identification resulting from this PCN:				
None.				
<b>Product Affected:</b>				
LM5170QPHPRQ1	LM5170QPHPTQ1			

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com