



Micron Technology, Inc.
8000 S. Federal Way
PO Box 6
Boise, ID United States

Specific MCP MPN Terminations

PCN: 31951

Published: 2016-06-02

Type:	End of Life
Description:	EOL of specific MCP (Multi Chip Package) Marketing Part Numbers. See Part Numbers listed. These specific part number EOL's do not affect any Design ID (DID) Micron MCP Product Roadmap timelines.
Reason:	Change in Market Demand, Manufacturing Efficiency
Product Affected:	See Marketing Part Numbers listed

Affected Micron Part Number	Recommended Replacement	Customer Part Number
<u>Component</u>		
MT29C1G12MAAIYAMD-5 IT		
MT29C1G12MAAJVAKC-5 IT		
MT29C1G12MAAJYAMD-5 IT		
MT38W201DAA033JZZI.X68		

*Materials that have been ordered are in **bold**.

Method of Identification:	Marketing Part Number
Micron Sites Affected:	All Sites
Last Purchase Date*:	2016-12-02

Last Shipment Date: 2017-06-02

*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.