Product Change Notification 32845 is complete and has been sent to approved customers. Please e-mail QA PCN SUPPORT@micron.com if you have any questions regarding this Product Change Notification.



Micron Technology, Inc. 8000 S. Federal Way PO Box 6 Boise, ID United States

J83G, J88F and J84Z MCP EOL

PCN: 32845

Published: 2018-07-11

Type:	End of Life		
Description:	Micron will end of life the following MCP products with no replacement:		
	 J83G MCP2 (162ball 2Gb M69A SLC NAND + 1Gb U98M LPDDR2) J88F MCP2 (162ball 2Gb M79A SLC NAND + 2Gb U98M LPDDR2) J84Z MCP3 (221ball 4Gb M60A SLC NAND + 8Gb V01M LPDDR3) 		
Reason:	Change in Market Demand		
Product Affected:	J83G, J88F, J84Z MCPs		
Affected Micron Part Number		Recommended Replacement	Customer Part Number
Component			
MT29RZ2B1DZZHGWD-18I.83G			
MT29RZ2B2DZZHHTB-18I.88F			
MT29UZ4B8DZZHGPB-107 W.84Z			
		*Materials that have been ordered a	are in bold .
Method of Identification:	Marketing Part Number		

Micron Sites Affected:	All Sites
Last Purchase Date*:	2019-01-11
Last Shipment Date:	2019-07-11

^{*}Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.