

1 Products affected

Product hierarchy no. *				Part no.	SBU	Product Type	Customer part no.
SBU	PG	PUG	Type				
02	007	002	0000002028	See appendix below		6100-3	
02	007	002	0000002029	See appendix below		6100-4	
02	007	002	0000002030	See appendix below		6100-9	
02	007	002	0000002031	See appendix below		6102-3	
02	007	002	0000002032	See appendix below		6102-5	
02	007	002	0000002033	See appendix below		6102-9	

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

- Change of label
- Change of configuration code

3 Detailed description of change

Current label	New label
<p>Current label configuration code: 610X-XXXX-XXXI-XX</p>	<p>New label configuration code: 610X-XXXX-XXX0-XX</p>

- Change of Configuration Code and therefore change on label

4 Reason of change

- Added digit to the Configuration Code for enlargement of product range in the future.

5 Release date

The change takes effect in ww 09/2023 (Date code 2309 or higher on label).
Parts on stock will be used upon depletion.

6 Impact of change and recommended action

- Form
- Fit
- Function
- Manufacturing
- Label New Configuration Code on label
- Packaging

Product Change Notification					PCN 6100 and 6102 Change on Configuration Code		
owner	creation date	release date	released by	change order	rev	page	D10-069-692
wiedersa	29.11.2022	05.12.2022	muehlema	2025146	A	1 of 2	

7 Reference Documents

Kind of document	Document Title
Data Sheet	Data Sheet 6100-3
Data Sheet	Data Sheet 6100-4
Data Sheet	Data Sheet 6102-3
Data Sheet	Data Sheet 6102-5

8 Appendix

List of part numbers affected for type 6100-3				
6100.3100	6100.3100.33.H	6100.3200.32	6100.3300.15	
6100.3100.02	6100.3200	6100.3200.33	6100.3300.32	
6100.3100.32	6100.3200.10	6100.3200.33.H	6100.3300.33	
6100.3100.33	6100.3200.15	6100.3300	6100.3300.33.H	

List of part numbers affected for type 6100-4				
3-100-352	6100.4110.01.G	6100.4125	6100.4216	6100.4315
3-104-141	6100.4110.G	6100.4125.G	6100.4220	6100.4315.01
3-104-209	6100.4112	6100.4130	6100.4220.15	6100.4315.15
3-122-776	6100.4115	6100.4130.G	6100.4225	6100.4315.24
3-123-865	6100.4115.17	6100.4210	6100.4230	6100.4320
6001.0008	6100.4115.G	6100.4210.15	6100.4308	6100.4320.15
6100.4108	6100.4120	6100.4212	6100.4310	6100.4325
6100.4110	6100.4120.G	6100.4215	6100.4310.01	6100.4330
6100.4110.01	6100.4120.Z	6100.4215.15	6100.4312	6100.4330.15

List of part numbers affected for type 6100-9				
6100.9100	6100.9100.13	6100.9200	6100.9300	

List of part numbers affected for type 6102-3				
6102.3100	6102.3200	6102.3300		

List of part numbers affected for type 6102-5				
3-100-749	6102.5125	6102.5225	6102.5225.16	6102.5320.15
6102.5110	6102.5130	6102.5225.01	6102.5230	6102.5325
6102.5112	6102.5210	6102.5225.011	6102.5310	6102.5330
6102.5115	6102.5215	6102.5225.014	6102.5312	
6102.5120	6102.5220	6102.5225.016	6102.5315	
6102.5120.051	6102.5220.051	6102.5225.15	6102.5320	

List of part numbers affected for type 6102-9				
6102.9100	6102.9200			

Product Change Notification					PCN 6100 and 6102 Change on Configuration Code		
owner	creation date	release date	released by	change order	rev	page	D10-069-692
wiedersa	29.11.2022	05.12.2022	muehlema	2025146	A	2 of 2	