

## **Product Change Notification (PCN)**

PCN Number 508634 Date Issued May 08, 2020

Reason for Change | Change to Product

Change Type Description | This letter is to inform you that changes are being made to the

part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example

of the possible differences.

Reason for Short Notice | Corrective Actions

Assessment of Change Product will be fully qualified before it is shipped. Qualification

reports will be available after below listed date

Internal Molex Qualification Date | May 08, 2020

Sample Availability Date (Changed Part) May 08, 2020

Planned Implementation Date | July 01, 2020

Method of Identifying Change Lot information on label

### After Change

#### Overview

Originally Molex CD have shipped the part with guide plate in pre-lock position. In that case, we could not inspect the pin Z position in final-lock position. Molex CD would like to ship with guide Plate in final-lock position so that we can inspect the pin Z position in final-lock position.







- Product Impact: no impact to fit, form or function
- Part Number Impact: see attached impacted parts list
- Qualification Reports and samples available upon request after the date shown above



## **Product Change Notification (PCN)**

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:508634" in the e-mail Subject line for faster response.

# RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com Molex Part #