



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000799

DATE: 27-Mar-2015

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAXQ616V-L000+T	N/A			Reactivation
Reactivation	MAX44244AUK+T	N/A			Reactivation
Reactivation	MAX44245ASD+T	N/A			Reactivation
Reactivation	MAX44245AUD+T	N/A			Reactivation
Reactivation	MAX311MJE/883B	N/A			Reactivation
Reactivation	MAX44245AUD+	N/A			Reactivation
Reactivation	MAX310MJE/883B	N/A			Reactivation
Reactivation	MAX19791EVKIT#	N/A			Reactivation
Reactivation	MAX19791ETX+	N/A			Reactivation
Reactivation	MAX19793ETX+T	N/A			Reactivation
Reactivation	MAX2062EVKIT#	N/A			Reactivation
Reactivation	MAX2063EVKIT#	N/A			Reactivation
Reactivation	MAX2837-RD0117	N/A			Reactivation
Reactivation	MAX2838-RD0142	N/A			Reactivation
Reactivation	MAX2838ETM+TG05	N/A			Reactivation
Reactivation	MAX19792ETX+	N/A			Reactivation
Reactivation	MAX19792ETX+T	N/A			Reactivation
Reactivation	MAX19792EVKIT#	N/A			Reactivation
Reactivation	MAX19793ETX+	N/A			Reactivation
Reactivation	MAX19793EVKIT#	N/A			Reactivation
Reactivation	MAX2062ETM+	N/A			Reactivation
Reactivation	MAX2062ETM+T	N/A			Reactivation
Reactivation	MAX2063ETM+	N/A			Reactivation
Reactivation	MAX2063ETM+T	N/A			Reactivation
Reactivation	MAX2064ETM+	N/A			Reactivation
Reactivation	MAX2064ETM+T	N/A			Reactivation

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 27-Apr-2015

Reactivation	MAX2064EVKIT#	N/A				Reactivation
Reactivation	MAX19791ETX+T	N/A				Reactivation
Reactivation	MAX2837-RD0087	N/A				Reactivation
Reactivation	MAX2837ETM+	N/A				Reactivation
Reactivation	MAX2837ETM+T	N/A				Reactivation
Reactivation	MAX2837EVKIT+	N/A				Reactivation
Reactivation	MAX2838ETM+	N/A				Reactivation
Reactivation	MAX2838ETM+T	N/A				Reactivation
Reactivation	MAX2838EVKIT+	N/A				Reactivation