

PCN Number:	20190409001.0	PCN Date:	April 22, 2019
Title:	Datasheet for THVD1419 THVD1429		
Customer Contact:	PCN Manager	Dept:	Quality Services
Proposed 1st Ship Date:	July 22, 2019		
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

The product datasheet(s) is being updated as summarized below.
The following change history provides further details.
The datasheet number will be changing.



THVD1419, THVD1429

SLLSF32C – NOVEMBER 2018 – REVISED MARCH 2019

Changes from Revision B (December 2018) to Revision C	Page
• Changed THVD1419 From: <i>Product Preview</i> To: <i>Production data</i>	1
• Changed power dissipation numbers of THVD1419	6
• Changed THVD1419 driver switching characteristics	8
• Changed THVD1419 receiver switching characteristics	8
• Added Figure 7 to Figure 9	9

The datasheet number will be changing.

Device Family	Change From:	Change To:
THVD1419 THVD1429	SLLSF32B	SLLSF32C

<http://www.ti.com/product/THVD1419>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

Electrical specification performance changes as indicated above.

Changes to product identification resulting from this PCN:

None.

Product Affected:

THVD1419DR	THVD1419DT	THVD1429DR	THVD1429DT
------------	------------	------------	------------

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com