

PCN-BCA-001937

Product Change Notice

Issue Date: May 14, 2020

Change Type:

Change from ink mark to laser mark

Parts Affected:

BCM6511IPBG

BCM6512IPBG

BCM6519IPBG

BCM6519RIPBG

Description and Extent of Change:

Marking method change from ink mark to laser mark

Reasons for Change:

Assembly house ink marking process phase out due to environment requirement.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The device specification will remain the same, which will ensure product electrical performance remains the same. Appropriate electrical characterization and reliability qualification has been performed on representative products to ensure normal parametric distribution, consistent electrical performance, and reliability.

Effective Date of Change:

Product shipments using this change will begin after 8/30/2020. Timing of shipment of the changed part will vary by part number depending on customer demand, and inventory levels.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.