

101 North Sepulveda Boulevard, El Segundo, California, 90245, USA Telephone: +1 310 726 8000 www.irf.com

Process Change Notification

Date: August 9, 2013

PCN Reference: S20898G

PCR Reference:

Product Reference: IRAM Product

To Our Valued Customer:

As always we appreciate your use of International Rectifier semiconductor products. Our commitment to customer satisfaction and continuous improvement is demonstrated by our change plans to enhance capacity, quality and reliability. This notice is to inform you of the following change:

Type of Change Notification:

Manufacturing factory relocation from SSV, Vietnam to OSV, Vietnam

Description of Change:

The production of the above part numbers will be transferred from SSV to OSV.

The lot code will distinguish the site as follows:

OSV: "xxHxx"

Reason for the Change:

As an on-going effort to consolidate factory locations to improve productivity, all IRAM production will be moved into a single location: OSV.

Effect Date:

November 8, 2013



International Rectifier will consider this change approved and will implement it by the effective date unless specific conditions of acceptance or data requests are provided in writing within 30 days of receipt of this notice. Please submit conditions of acceptance and data requests to the PCN coordinator listed at the end of this notice.

Impact of Change:

There will be no impact to the fit, form, function, quality or reliability of the parts. There will be no change to the datasheet parameters.

Products Affected:

IRAMS06UP60A	IRAMS06UP60A-2	IRAMS06UP60B	
IRAMS06UP60B-2	IRAMS10UP60A	IRAMS10UP60A-2	
IRAMS10UP60B	IRAMS10UP60B-2	IRAMS12UP60A	
IRAMS12UP60A-2	IRAMX16UP60A	IRAMX16UP60A-2	
IRAMX16UP60B	IRAMX16UP60B-2	IRAMX20UP60A	
IRAMX20UP60A-2	IRAMY20UP60B	IRAM136-3023B	
IRAM136-3063B	IRAM136-1061A	IRAM136-1061A2	
98-0290			

Qualification:

Parts have completed our reliability testing requirements. Reliability qualification report will be available upon request. Qualification standards can be found on International Rectifier's web site at www.irf.com/product-info/reliability.

Data Availability:

Please contact the PCN Coordinator for supporting data.

Contact Information:

CONTACT TYPE	NAME	PHONE	EMAIL
PCN Coordinator	John Michaelson	951 375-4432	mailto:jmichae2@irf.com
Technical	Chia Lin	310 252-7805	Clin1@irf.com