

Eaton
Electronics Division
5735 W. Las Positas Blvd #100
Pleasanton, CA 94588
www.eaton.com/electronics

Product Change Notice

PCN#: EE-PCN18005 1/31/2018

CLASSIFICATION OF CHANGE:

Label tape shape update

DESCRIPTION OF CHANGE:

Reposition cut corner of label tape from top left to bottom left.

REASON FOR CHANGE:

To improve recognition of orientation for AOI system



EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

PARTS FAMILIES AFFECTED:

CLB1108-2-50TR-R	CL0608-2-100TR-R	FPD1110V2-R300-R
CLB1108-3-50TR-R		
CLB1108-4-50TR-R		
CLB1108-5-50TR-R		

TIME SCHEDULE:

Start Shipment Date: Effective immediately

SAMPLE AVAILABILITY:

Available upon request

QUALIFICATION DATA:

Available upon request

ISSUED BY:

Global Product Manager: Subiry Steve

CONTACT INFORMATION:

For questions or comments, please contact your local **Eaton sales representative**.