



## QUALITY ALERT: PRODUCT RECALL

**QAlert-000151**

**Date: 02-13-2023**

P1/2

Semtech Corporation, 200 Flynn Road, Camarillo CA 93012

### Recall Details

**Recall Notification:**

Semtech Corporation has reported a potential issue with the product identified below which has been shipped to you. The shipments could contain discrepant devices. Semtech is advising you of this potential discrepant product and instructs you to contain all material subject to this alert. You should immediately cease using the discrepant devices listed below and contain any of your products that may have used this material.

**Part Number(s) Affected:**

- TS32101-QFNR

**Customer Part Number(s) Affected:**  N/A

**Recall Description:**

- Lot Numbers= 433804.1, 433804.1M & 433808.1M
- Date Code = 2252
- Semtech's Quality team has isolated this issue to one of our assembly and test suppliers. A Supplier Corrective Action will be initiated to determine root cause and corrective actions.
- Semtech asks that any **unused** material identified above be returned to the addressed listed below for replacement.

**Case Reference**

N/A

**FA Report Reference**

N/A

**RMA Reference**

N/A\*

**SCAR or CAPA Ref.**

SCAR-002522  N/A

### Instructions to Return Material

**Return material to:**

**Attn: Chen Wen Lee  
 Carsem Semiconductor Sdn B  
 Lot 52986 Taman Meru Industrial Estate  
 Jelapang, 30720 Ipoh, Perak Malaysia**




## QUALITY ALERT: PRODUCT RECALL

**QAlert-000151**

**Date: 02-13-2023**

P2/2

Issuing Authority	
<b>Semtech Business Unit:</b>	Power Management
<b>Semtech Contact Info:</b>	<p><i>Carlos Sierra</i> Quality Assurance Semtech Corporation 200 Flynn Road Camarillo, CA, 93012 <a href="mailto:csierra@semtech.com">csierra@semtech.com</a></p> 
FOR FURTHER INFORMATION & WORLDWIDE SALES COVERAGE: <a href="http://www.semtech.com/contact/index.html#support">http://www.semtech.com/contact/index.html#support</a>	