



Not Recommended for New Design: LA Series Relays

NRFND.PG0006.12.26.2018

12.26.2018

About This Notice:	Panasonic LA Series Relays have changed status to Not Recommended For New Design due to possible plans for discontinuation in the future.
Features:	
Effective Date:	Immediate
Affected Parts and/or Replacements:	See attached. There are no direct replacements.
Datasheet(s):	See attached.
Notes:	

Affected Parts

ALA2F4H

ALA2F05

ALA2F09

ALA2F12

ALA2F18

ALA2F24

ALA2F24T

ALA2FB12

ALA2PF4H

ALA2PF05

ALA2PF5T

ALA2PF5V

ALA2PF09

ALA2PF12

ALA2PF12T

ALA2PF12V

ALA2PF18

ALA2PF24

ALA2PF24T

ALA2PF24V