



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M001083

DATE: 03-Oct-2022

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX406ACPA+	N/A	03-Oct-2023	31-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX406AEPA+	N/A	03-Oct-2023	31-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX406BEPA+	N/A	03-Oct-2023	31-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX409ACPA+	N/A	03-Oct-2023	31-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX409BCPA+	N/A	03-Oct-2023	31-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX412BCPA+	N/A	03-Oct-2023	31-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX412CPA+	N/A	03-Oct-2023	31-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX412EPA+	N/A	03-Oct-2023	31-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX4167EPA+	N/A	03-Oct-2023	31-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX4168EPD+	N/A	03-Oct-2023	31-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX492EPA+	N/A	03-Oct-2023	31-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX494CPD+	N/A	03-Oct-2023	31-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX944CPD+	N/A	03-Oct-2023	31-Mar-2024	Part can no longer be manufactured
Discontinuance	TOSV-SENSOR-REF	N/A	03-Oct-2022	03-Oct-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 03-Nov-2022