

PCN-237749

Product Change Notice

Issue Date: 20-September-2021

Change Description:

Alternate manufacturing site for ChipLED part numbers listed below.

Parts Affected:

BSMA-C130-000BB	HSMR-C130-00001	QSMR-C13G
BSMC-C130-000A5	QSMC-C132	QSMR-C13L
BSMC-C132	QSME-C131	QSMR-C13N
BSML-C136-000AA	QSME-C132	QSMR-C13Q
BSMR-C13U	QSME-C133	QSMR-C13S
HSMA-C130	QSMR-C130-QRBC0	QSMR-C13T
HSMC-C130	QSMR-C131-00001	QSMR-C13U
HSME-C130	QSMR-C132	QSMR-C13V
HSML-C130	QSMR-C133	QSMR-C13W
HSMQ-C130	QSMR-C139	QSMR-C14A
HSMR-C130	QSMR-C13F	QSMR-R13A

Description and Extent of Change:


The alternate manufacturing site is qualified per Broadcom's qualification process.

Reasons for Change:

Assurance of supply.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change on fit, form, function, quality and reliability as per datasheet. There is a change on the country of origin (COO) on the label.





Effective Date of Change:

Effective from 20-December-2021, shipment may contain parts from existing or alternate manufacturing site.

Qualification Data:

Qualification data will be provided upon request.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.