Notification Number: 20160721001			Notification Date: 07/25/2016				
Title: Datasheet for TPS43333-Q1							
Customer Contact: PCN	Manager	Dept:	Quality Services				
Change Type:							
Assembly Site		Design				Wafer Bump Site	
Assembly Process		Data Sheet			Wafer Bump Material		
Assembly Materials		Part number change				Wafer Bump Process	
Mechanical Specification		Test Site				Wafer Fab Site	
Packing/Shipping/Labeling		Test Process				Wafer Fab Materials	
					Wafer Fab Process		
Notification Details							
Description of Change:							
Texas Instruments Incorporated is announcing an information only notification.							
The product datasheet(s) is updated as seen in the change revision history below:							
TEXAS							
TEXAS INSTRUMENTS							
TPS43333-Q1							
SLVSB48C – AUGUST 2012–REVISED JULY 2016 www.ti.com							
Changes from Revision B (April 2013) to Revision C Page							
Added Pin Configuration and Functions section, ESD Ratings table, Feature Description section, Device Functional							
Modes, Application and Implementation section, Power Supply Recommendations section, Layout section, Device							
and Documentation Support section, and Mechanical, Packaging, and Orderable Information section							
Deleted Ordering Information table; see POA at the end of the data sheet							
Changed Inductor value from 4 µH to 3.9 µH							
Deleted Application Example 2; Renamed Application Example 3							
The datasheet number will be changing.							
Device Family			Change From:		Change To:		
TPS43333-Q1		SLVSB48B			SLVSB48C		
These changes may be reviewed at the datasheet links provided.							
http://www.ti.com/lit/ds/symlink/tps43333-q1.pdf							
Reason for Change:							
To more accurately reflect device characteristics.							
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):							
No anticipated impact. This is a specification change announcement only. There are no changes							
to the actual device							
Changes to product identification resulting from this notification:							
None.							
Product Affected:							
TPS43333QDAPRQ1							
For questions regarding this notice, e-mails can be sent to the regional contacts shown below							
or your local Field Sales Representative.  E-Mail							
Location						t ti com	
USA			PCNAmericasContact@list.ti.com PCNEuropeContact@list.ti.com				
			siaContact@list.ti.com				
Japan	apan <u>PCNJapanContact@list.ti.com</u>						