

EOL: EOL-CSG-42615-001-0

Product Obsolescence Notification, without pin-compatible replacement

Issue Date: 10/17/2016

Broadcom Limited is announcing the obsolescence of the following products:

Broadcom Part Numbers	Description	LTB Date (LTB)	LTS Date (LTS)	Minimum Order (MOQ)
BCM56014A2KFEB1G	Switch	4/15/2017	10/15/2017	306
BCM56018A2KFEB1G	Switch	4/15/2017	10/15/2017	306
BCM56018SB08	Switch	4/15/2017	10/15/2017	306
BCM56214A2KFEB	Switch	4/15/2017	10/15/2017	306
BCM56214A2KFEBG	Switch	4/15/2017	10/15/2017	306
BCM56214SN01	Switch	4/15/2017	10/15/2017	306
BCM56214SP01	Switch	4/15/2017	10/15/2017	306
BCM56218A2KFEBG	Switch	4/15/2017	10/15/2017	306
BCM56300B1IEB	Switch	4/15/2017	10/15/2017	334
BCM56300B1IEBG	Switch	4/15/2017	10/15/2017	334
BCM56300B1KEB	Switch	4/15/2017	10/15/2017	334
BCM56300B1KEBG	Switch	4/15/2017	10/15/2017	334
BCM56300B1KEBLG	Switch	4/15/2017	10/15/2017	334
BCM56302B1IEB	Switch	4/15/2017	10/15/2017	334
BCM56302B1KEBG	Switch	4/15/2017	10/15/2017	334
BCM56302B1IEBLG	Switch	4/15/2017	10/15/2017	334
BCM56302B1KEBLG	Switch	4/15/2017	10/15/2017	334
BCM56310A0KFEBG	Switch	4/15/2017	10/15/2017	328
BCM56312A0IFEBG	Switch	4/15/2017	10/15/2017	328
BCM56312A0KFEBG	Switch	4/15/2017	10/15/2017	328
BCM56312SN01	Switch	4/15/2017	10/15/2017	328
BCM56314A0KFEBG	Switch	4/15/2017	10/15/2017	328
BCM56315A0KFEBG	Switch	4/15/2017	10/15/2017	328
BCM56319SH01	Switch	4/15/2017	10/15/2017	328
BCM56319A0KFEBG	Switch	4/15/2017	10/15/2017	328
BCM56500B2IEB	Switch	4/15/2017	10/15/2017	220
BCM56500B2IEBG	Switch	4/15/2017	10/15/2017	220
BCM56500B2KEBG	Switch	4/15/2017	10/15/2017	220
BCM56500B2IEBLG	Switch	4/15/2017	10/15/2017	220
BCM56500B2KEBLG	Switch	4/15/2017	10/15/2017	220



DRUADCOM				
BCM56501B2KEBG	Switch	4/15/2017	10/15/2017	220
BCM56501B2KEBLG	Switch	4/15/2017	10/15/2017	220
BCM56502B2IEB	Switch	4/15/2017	10/15/2017	220
BCM56502B2KEBG	Switch	4/15/2017	10/15/2017	220
BCM56502B2IEBLG	Switch	4/15/2017	10/15/2017	220
BCM56502SBC01	Switch	4/15/2017	10/15/2017	220
BCM56502SBL01	Switch	4/15/2017	10/15/2017	220
BCM56503B2KEBG	Switch	4/15/2017	10/15/2017	220
BCM56503B2KEBLG	Switch	4/15/2017	10/15/2017	220
BCM56504B2IEB	Switch	4/15/2017	10/15/2017	220
BCM56504B2KEBG	Switch	4/15/2017	10/15/2017	220
BCM56504B2KEBLG	Switch	4/15/2017	10/15/2017	220
BCM5650IPB	Switch	4/15/2017	10/15/2017	220
BCM5650KPBG	Switch	4/15/2017	10/15/2017	496
BCM5650SCA01	Switch	4/15/2017	10/15/2017	496
BCM5650SCE01	Switch	4/15/2017	10/15/2017	496
BCM5650SCH01	Switch	4/15/2017	10/15/2017	496
BCM56510A0KFEBG	Switch	4/15/2017	10/15/2017	172
BCM56510A0IFEBLG	Switch	4/15/2017	10/15/2017	172
BCM56510A0KFEBLG	Switch	4/15/2017	10/15/2017	172
BCM56512A0KFEBG	Switch	4/15/2017	10/15/2017	172
BCM56512A0KFSBLG	Switch	4/15/2017	10/15/2017	172
BCM56512SAE01	Switch	4/15/2017	10/15/2017	172
BCM56512SAF01	Switch	4/15/2017	10/15/2017	172
BCM56512SB00	Switch	4/15/2017	10/15/2017	172
BCM56512SC01	Switch	4/15/2017	10/15/2017	172
BCM56512SG01	Switch	4/15/2017	10/15/2017	172
BCM56514A0IFEBG	Switch	4/15/2017	10/15/2017	172
BCM56514A0KFEB	Switch	4/15/2017	10/15/2017	172
BCM56514A0KFEBG	Switch	4/15/2017	10/15/2017	172
BCM56514A0IFEBLG	Switch	4/15/2017	10/15/2017	172
BCM56514A0KFEBLG	Switch	4/15/2017	10/15/2017	172
BCM56514SCX01	Switch	4/15/2017	10/15/2017	172
BCM56514SCY01	Switch	4/15/2017	10/15/2017	172
BCM56514SCZ01	Switch	4/15/2017	10/15/2017	172
BCM56514SDR01	Switch	4/15/2017	10/15/2017	172
BCM56514SEM01	Switch	4/15/2017	10/15/2017	172
BCM56514SEQ01	Switch	4/15/2017	10/15/2017	172
BCM56514SF00	Switch	4/15/2017	10/15/2017	172
BCM56519A0KFEBG	Switch	4/15/2017	10/15/2017	172
BCM56519A0KFEBLG	Switch	4/15/2017	10/15/2017	172
BCM5651KPBG	Switch	4/15/2017	10/15/2017	496
BCM5651SCK01	Switch	4/15/2017	10/15/2017	496
BCM5651SCP01	Switch	4/15/2017	10/15/2017	496
BCM56580A0KFEBG	Switch	4/15/2017	10/15/2017	200
BCM56700A0KFEBG	Switch	4/15/2017	10/15/2017	200

Doc Num: EOL-CSG-42615-001-0



BCM56800A0IFEBG	Switch	4/15/2017	10/15/2017	200
BCM56800A0KFEBG	Switch	4/15/2017	10/15/2017	200
BCM56800SAB01	Switch	4/15/2017	10/15/2017	334
BCM56304B1KEBG	Switch	4/15/2017	10/15/2017	334
BCM56304B1KEBLG	Switch	4/15/2017	10/15/2017	334
BCM56801SE01	Switch	4/15/2017	10/15/2017	328
BCM56317A0KFEBG	Switch	4/15/2017	10/15/2017	328
BCM56802A0KFEBG	Switch	4/15/2017	10/15/2017	200
BCM56820SBL01	Switch	4/15/2017	10/15/2017	172
BCM56512A0IFEBG	Switch	4/15/2017	10/15/2017	172
BCM56512A0KFSBLG	Switch	4/15/2017	10/15/2017	172
BCM56820SEV01	Switch	4/15/2017	10/15/2017	172
BCM5695B0IPBG	Switch	4/15/2017	10/15/2017	389
BCM5695B0KPB	Switch	4/15/2017	10/15/2017	389
BCM5696B0IPB	Switch	4/15/2017	10/15/2017	389
BCM5696B0KPB	Switch	4/15/2017	10/15/2017	389
BCM5697B0KPBG	Switch	4/15/2017	10/15/2017	389
BCM88440B0KFSBG	Switch	4/15/2017	10/15/2017	108
BCM88440B0KSFBLG	Switch	4/15/2017	10/15/2017	108
BCM88540B0KFSBG	Switch	4/15/2017	10/15/2017	108
BCM88540B0KFSBLG	Switch	4/15/2017	10/15/2017	108
DN-FE6001DVA0	Switch	4/15/2017	10/15/2017	211

Please provide your Broadcom Limited Sales Office with your lifetime Last Time Buy order requirements (LTB) for the above products no later than the date noted in the above table. These orders are non-cancelable, non-returnable and cannot be rescheduled. Orders received after the Last Time Buy order (LTB) date noted in the above table cannot be accepted.

The last requested delivery date for these orders may not be later than the LTS date noted in the above table. Due to inherent variations in yields, Broadcom Limited reserves the right to ship up to 5% under the original last time buy quantity, and this quantity will fully satisfy Broadcom Limited's obligation to deliver that product under this last time buy agreement.

All last time buy orders must be placed based on Broadcom Limited's minimum order quantity requirements per the above table. All prior commitments regarding Broadcom Limited minimum order requirements do not apply to last time buy orders. Broadcom Limited reserves the right to limit last time buy quantities based on capacity and material availability.

Please contact your Broadcom Limited field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.