

Search ...

PRODUCTS | APPLICATIONS | DESIGN SUPPORT | TRAINING | SAMPLE AND BUY | ABOUT US | CONTACT US | myMicrochip Login

Product Change Notification - SYST-13DJTM862

Date: 14 Sep 2016 SMSC **Product Category: 7** Affected CPNs:

Notification subject: Data Sheet - LAN8810/LAN8810i - GMII 10/100/1000 Ethernet Transceiver w/HP Auto-MDIX

Support Data Sheet Document Revision

Notification text: SYST-13DJTM862

> Microchip has released a new DeviceDoc for the LAN8810/LAN8810i - GMII 10/100/1000 Ethernet Transceiver w/HP Auto-MDIX Support of devices. If you are using one of these devices please read the document located at LAN8810/LAN8810i - GMII 10/100/1000 Ethernet Transceiver w/HP Auto-MDIX Support.

Notification Status: Final

Description of Change:

- 1) Corrected grammar, spelling, and formatting inconsistencies throughout the document. 2) Trademark and Sales office listings updated.
- 3) Updated image in Figure 3.4.
- 4) Reduced XI Absolute Maximum input voltage level to +3.6V in Section 5.1.
- 5) Reduced XI Minimum Input High level to 0.9V in Table 5-7.
- 6) Updated links to go to the correct referenced note numbers in Table 5-20.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability Change Implementation Status: Complete Date Document Changes Effective: 14 Sep 2016

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

LAN8810/LAN8810i - GMII 10/100/1000 Ethernet Transceiver w/HP Auto-MDIX Support Attachment(s):

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at http://www.microchip.com/PCN sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to microchipDIRECT and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."







Products | Applications | Design Support | Training | Sample and Buy | About Us | Contact Us | Legal | Investors | Careers | Support

SYST-13DJTM862 - Data Sheet - LAN8810/LAN8810i - GMII 10/100/1000 Ethernet Transceiver w/HP Auto-MDIX Support Data Sheet Document Revision

Affected Catalog Part Numbers (CPN)

LAN8810I-AKZE-TR LAN8810I-AKZE

LAN8810-AKZE-TR

LAN8810-AKZE

Date: Tuesday, September 13, 2016