

Final Product Change Notification

202104052F02 : SOT505-2 Assembly Transfer from ATP to ATBK

Note: This notice is NXP Company Proprietary.

Issue Date: Nov 24, 2021 Effective date:Mar 04, 2022

Here is your personalized notification about a NXP general announcement. For detailed information we invite you to view this notification online

Management summary

SOT505-2 assembly will be discontinued at ATP and ATBK is adding SOT505-2 assembly to maintain supply.

Change Category

[]Wafer Fab Process	[]Assembly Process	[]Product Marking	[]Test Process	[]Design
[]Wafer Fab Materials	[X]Assembly Materials	[]Mechanical Specification	[]Test Equipment	[]Errata
[]Wafer Fab Location	[X]Assembly Location	[X]Packing/Shipping/Labeling	[]Test Location	[]Electrical spec./Test coverage
[]Firmware	[]Other			

[]Firmware []Other

PCN Overview Description

NXP has extensive manufacturing capabilities in the TSSOP8 family, to which will be further expanded to include the part types in the attached file list. Mold compound and die adhesive materials in the ATBK manufacturing process will use the standard EMC-7470L-Q and QMI519 materials respectively. Additionally, ATBK will employ a roughened leadframe as a package quality improvement to reduce delamination. From the change associated to the

'Packing/Shipping/Labeling', only the 'label' will change. It will reflect the appropriate ATBK assembly information that is standard on their labeling.

Reason

Due to an increasing demand for SOT505-2 packaged devices and ATP discontinuance of supply over time, NXP is adding the ATBK flow to enable supply.

Identification of Affected Products

Product identification does not change

Product Availability

Sample Information Samples are available upon request Production

Planned first shipment Mar 04, 2022 Anticipated Impact on Form, Fit, Function, Reliability or Quality

No Impact on form, fit, function, reliability or quality Data Sheet Revision No impact to existing datasheet Disposition of Old Products Existing inventory will be shipped until depleted Timing and Logistics

In compliance with JEDEC J-STD-046, your acknowledgement of this change is expected by Dec 24, 2021.

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name	Dennis Dill			
Position	QE Engineer			
e-mail address	dennis.dill@nxp.com			

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply .

NXP Semiconductors High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006- 2021 NXP Semiconductors. All rights reserved.

Changed Orderable Part#	12NC	Product Type	Product Description	Package Outline	Package Description	Product Status	Customer Specific Indicator	Product Line
NTS0102DP-Q100H	935300555125	NTS0102DP-Q100	Xlator w/auto dir & open drain	(T)SSOP8	SOT505-2	RFS	No	BLC6
NTB0102DP-Q100H	935300866125	NTB0102DP-Q100	Xlator transceiver auto sensing	(T)SSOP8	SOT505-2	RFS	No	BLC6
NTS0102DP,125	935293487125	NTS0102DP	Xlator w/auto dir & open drain	(T)SSOP8	SOT505-2	RFS	No	BLC6
NTB0102DP,125	935293473125	NTB0102DP	Dual-supply Xlator w/auto dir	(T)SSOP8	SOT505-2	RFS	No	BLC6
NCX2220DP,125	935297651125	NCX2220DP	Dual Low Voltage Comparator	(T)SSOP8	SOT505-2	DOD	No	BLC6
PCA9306DP1,125	935283122125	PCA9306DP1	PCA9306	(T)SSOP8	SOT505-2	RFS	No	BLC6