DC	NI BL	m h o u	20	170025	001	<u> </u>	DON Dates			0+ 2 2017			
PCN Number: Title: Datasheet for				170925		TDCC212	PCN Date: TPS62133A-Q1, TPS621			Oct. 2, 2017			
			_			, IPS6213.	3A-Q1, 1PS62				0 111 0 :		
Customer Contact: PCN Manager							Dej			ept: Quality Services			
Cha		Type:									5 0"		
Щ	Assembly Site					Design			4		er Bump Site		
Щ				=				4		er Bump Material			
Н	Assembly Materials			Part number change			_		er Bump Process				
Н				Test Site			4		er Fab Site				
Packing/Shipping/Labeling			Test Process			_		er Fab Materials					
					ification Details			Wafer Fab Process					
Notification Details													
	Description of Change: Texas Instruments Incorporated is announcing an information only notification.									ion.			
									110	uncai	.1011.		
	The product datasheet(s) is being updated as summarized below.												
ine	The following change history provides further details.												
TEXAS TPS62130A-Q1, TPS62133A-Q1, TPS62130									3A-Q1, TPS6213013A-Q1				
	114	STROMENTS							SL	VSCC20	-MAY 2014-REVISED JULY 2017		
С	Changes from Revision B (October 2016) to Revision C												
_	Tage												
•	Added WEBENCH® links throughout document												
•	 Changed "LOG" pin to "FSW" pin on the Pin Configuration and Functions and added FSW description throughout 												
	the document												
•	Added SW (AC) spec to the Absolute Maximum Ratings table. 4												
_													
The	data	sheet number	will	he chan	aina	_							
The datasheet number will be of Device Family			oc ciiaii	Change From:				Change To:					
,										3			
TPS62130A-Q1, TPS62133A-Q1,				SLVSCC	SLVSCC2B			SLVS	CC2C				
		.3013A-Q1											
These changes may be reviewed at the datasheet links provided.													
http://www.ti.com/product/TPS62130A-Q1													
Reason for Change:													
To accurately reflect device characteristics.													
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):													
No anticipated impact. This is a specification change announcement only. There are no changes													
to the actual device. Changes to product identification resulting from this PCN:													
Cha	ange	s to product	iden	tificatio	on re	esulting fi	om this PCN	1 :					
Noi	None.												
Pro	oduct	Affected:											
TP	S621	3013AQRGTRQ1		TPS621	3013	AQRGTTQ1	TPS62130	AQR	GTI	RQ1	TPS62130AQRGTTQ1		
	TPS62133AQRGTRQ1			TPS62133AQRG						-	, ,		
Ц'''	11302133AQROTRQ1 11302133AC												

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com