

Part Termination Notification

Date: May 9, 2014 Change Notification No. PCN 2014-0003_SOJ & SOP

From: ISSI-Integrated Silicon Solution, Inc.

Products Affected:

IS63LV1024, IS61LV6416, IS61C1024AL, IS62C1024AL, IS61C6416AL, IS65C1024AL in 32-pin 300-mil SOJ, 32-pin 400-mil SOJ, 32-pin 450-mil SOP or 44-pin 400-mil SOJ packages.

Reason for the Termination: Due to limited demand, we will stop SnPb plating assembly service and convert SnPb material into lead free material. We will continue to produce lead-free packages.

Last Time Buy: Oct 1, 2014

Last Time Shipment: December 31, 2014

Please contact marketing at sram@issi.com for further information.