

Title of Change:	4Q2021 Product Discontinuance Notice - Batch 4 (Standard)
Last Time Buy Date:	21 Jun 2022
Last Ship Date:	21 Dec 2022
Contact information:	Contact your local onsemi Sales Office or PCN.Support@onsemi.com
Type of notification:	Customers must notify onsemi (< PCN.Support@onsemi.com >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

Description and Purpose:

In an attempt to minimize the number and frequency of product discontinuance notices to its customers, onsemi is publishing this quarterly product discontinuance notification.

Some of the devices contained in this notice may be part of a product portfolio renewal process or a manufacturing facility closure. onsemi continually monitors worldwide sales and billings activities on all the products offered to its customers.

The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products or the manufacturing facility has been announced for a closure. Some devices may have an alternate standard device or a suggested replacement as an alternative solution.

onsemi wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

onsemi has provided a list of replacement devices, where available, to aid in this process.

For those devices that have no recommended replacement identified, onsemi has partnered with Rochester Electronics and Flip Electronics who will carry any remaining device inventory to potentially allow for a continued source after onsemi has completed its business process

PLEASE NOTE: onsemi may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel (tom.siegel@onsemi.com)

☎ +1 765 868 5022

USA

Japan:

Isao Usuki (isao.usuki@onsemi.com)

☎ +81 3 6880 1771

Japan

Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)

☎ +421 33790 2229

Slovakia

Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)

☎ +852 2689 0209

China

NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, onsemi ALLOWS SIX (6) MONTHS FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

Device to be Discontinued	Replacement part	Supplier
SBCP68T1G	NSVBCP68T1G	onsemi
NRVTSS5100ET3G	#NONE	#NA
74LCX245WMX	MC74LCX245DWR2G	onsemi
FQB33N10TM	FQB33N10LTM	onsemi
FDS2672-F085	#NONE	#NA
SVD5865NLT4G	NVD5C684NLT4G	onsemi
FQP3N50C-F080	FQP13N50C	onsemi
FQPF9N50CF	FQPF380N65FL1-F154	onsemi
FQP6N90C	FQP9N90C	onsemi
FQPF4N90C	FQPF9N90CT	onsemi
FQPF8N80C	FQP8N80C	onsemi
NCV81276MNTXG	#NONE	#NA
NTS260ESFT1G	#NONE	#NA
FQD10N20CTM	FQD10N20LTM	onsemi
FQP13N50	FCP360N65S3R0	onsemi
FQD2N60CTM	FQD3N60CTM-WS	onsemi
74VHC574MX	MC74VHC574DWR2G	onsemi
FQP4N90C	FQP9N90C	onsemi
MM74HC574WMX	MC74HC574ADWR2G	onsemi
74VHC245MX	MC74VHC245DWR2G	onsemi
SURS8320T3G	SURS8320T3G-VF01	onsemi
NCV4299D233R2G	NCV4299CD233R2G	onsemi
FDZ451PZ-P	#NONE	#NA
MDB10SS	#NONE	#NA
FDG6332C-PG	#NONE	#NA
MC33368DG	MC33368DR2G	onsemi
FDP20N50	FCP165N65S3	onsemi
MT9M015D00STCC14EC1-200	#NONE	#NA
FDZ1416NZ	#NONE	#NA
FDZ191P	#NONE	#NA
NCP6904FFCCT1G	#NONE	#NA
NCP6904EFCCT1G	#NONE	#NA
NCP6904DFCCT1G	#NONE	#NA

NCP6904FCCT1G	#NONE	#NA
NCP3901FCCT1G	#NONE	#NA
FDMF5812	#NONE	#NA
FDMF5808A	#NONE	#NA
FDMF5804	#NONE	#NA
SC2903DR2G	LM2903DR2G	onsemi
NTDV20P06LT4G-VF01	#NONE	#NA
NVMFD5877NLWFT1G	NVMFD5C680NLWFT1G	onsemi
NVMFD5489NLWFT1G	NVMFD5C680NLWFT1G	onsemi
NVMFS5826NLWFT1G	NVMFS5C680NLWFT1G	onsemi
FDWS9508L-F085	NVMFS3D0P04M8LT1G	onsemi
FDD9407-F085	NVD5C434NT4G	onsemi
NVD5890NLT4G-VF01	NVD5C454NLT4G	onsemi
NCV302LSN30T1G	#NONE	#NA
SCV2901DR2G	NCV2901DR2G	onsemi
HUFA76413DK8T-F085P	NVMFD5C680NLT1G (not p2p replacement)	onsemi
NCV8501DADJR2G	#NONE	#NA
NCV305LSQ23T1G	#NONE	#NA
MC100ELT22DG	MC100EPT22DG	onsemi
FSDM0565REWDTU	NCP12400(Controller)	onsemi
SB530	#NONE	#NA
FDWS9510L-F085	NVMFS014P04M8LT1G	onsemi

Appendix A: Changed Products
PCN#: PD24419ZB
Issue Date: Dec 20, 2021

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
SBCP68T1G			NSVBSP68T1G	onsemi
74LCX245WMX			MC74LCX245DWR2G	onsemi
FQB33N10TM			FQB33N10LTM	onsemi
SVD5865NLT4G			NVD5C684NLT4G	onsemi
FQP3N50C-F080			FQP13N50C	onsemi
FQPF9N50CF			FCPF380N65FL1-F154	onsemi
FQP6N90C			FQP9N90C	onsemi
FQPF4N90C			FQPF9N90CT	onsemi
FQPF8N80C			FQP8N80C	onsemi
NTS260ESFT1G			#NONE	#NA
FQD10N20CTM			FQD10N20LTM	onsemi
FQP13N50			FCP360N65S3R0	onsemi
FQD2N60CTM			FQD3N60CTM-WS	onsemi
74VHC574MX			MC74VHC574DWR2G	onsemi
FQP4N90C			FQP9N90C	onsemi
MM74HC574WMX			MC74HC574ADWR2G	onsemi
74VHC245MX			MC74VHC245DWR2G	onsemi
SURS8320T3G			SURS8320T3G-VF01	onsemi
NCV4299D233R2G			NCV4299CD233R2G	onsemi
MC33368DG			MC33368DR2G	onsemi
FDP20N50			FCP165N65S3	onsemi
FDZ1416NZ			#NONE	#NA
FDZ191P			#NONE	#NA
NCP3901FCCT1G			#NONE	#NA
NVMFD5877NLWFT1G			NVMFD5C680NLWFT1G	onsemi
NVMFS5826NLWFT1G			NVMFS5C680NLWFT1G	onsemi
FDWS9508L-F085			NVMFS3D0P04M8LT1G	onsemi
FDD9407-F085			NVD5C434NT4G	onsemi
NCV8501DADJR2G			#NONE	#NA
MC100ELT22DG			MC100EPT22DG	onsemi
FSDM0565REWDTU			NCP12400(Controller)	onsemi
SB530			#NONE	#NA
FDWS9510L-F085			NVMFS014P04M8LT1G	onsemi
NRVTSS5100ET3G			#NONE	#NA