Product Discontinuance Notice - PDN 16_0075 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

	Discontinuation	of All HMC398	Models
--	-----------------	---------------	--------

Publication Date:	27-Oct-2016
Last Time Buy Date:	28-Apr-2017
Last Time Ship Date:	31-Oct-2017
Revision Description:	
Initial Dalassa	

Initial Release

Reason For Discontinuance

Due to loss of lead frame supplier and decreased customer demand, ADI will discontinue all models of the HMC398 product. Due to this loss of manufacturing capability, ADI is offering a Last Time Buy based on available material in stock.

Supporting Documents None

	For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representitive					
Americas:	PDN_Americas@analog.com	Europe:	PDN_Europe@analog.com	Japan: Rest of Asia:	PDN_Japan@analog.com PDN_ROA@analog.com	

PDN 16_0075 Discontinued Parts Material List					
Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments	
HMC398QS16G	HMC398	HMC632LP5E	No		
HMC398QS16GE	HMC398	HMC632LP5E	No		
HMC398QS16GETR	HMC398	HMC632LP5ETR	No		
HMC398QS16GTR	HMC398	HMC632LP5ETR	No		

Appendix A - PDN 16_0075 Revision History						
Rev	Publish Date	ate Rev Description				
Rev	27-Oct-2016	Initial Release				
			Analog Devices, Inc. Proprietary Information	Docld:1093	Layout Rev:2	Parent Docld:None

Analog Devices, Inc. PDN 16_0075_Rev_- Page 2 of 2