

Advance Silicon Group (ASG) Pressure Sensor Migration

Summary

This is to inform you that effective **August 31, 2016**, Honeywell will no longer offer some of its Advance Silicon Group board mount pressure sensors due to supply chain discontinuity of a key component in the ASG product. The affected product families include CPCL, CPXL, CPC, DXL, DUXL DCXL, SCDA, XPCL, XPC, XCX, XCXL and XSCL Series. Honeywell is requesting that its existing customers migrate to an alternate part (see Appendix, page 2) in current and/or new applications.

Important Actions

Honeywell sales team and Authorized Distributors: Please inform affected customers as soon as possible. By **May 31, 2016**, provide the Honeywell regional product manager (see page 2) with the customer's preferred transition option:

Transition Options:

Option A: Migration to Replacement Product: Information required:

- a) Current product
- b) Migration product
- c) Total quantity of current product required. Example: 2 years of Estimated Annual Usage (EAU) to cover validation period.
- d) Effective date of migration
- e) What type of qualification data is required for validation to support the customer's chosen migration part?

Option B: Last Time Buy of Current Product: Information required (use spreadsheet provided):

- a) Current product
- b) Total quantity of current product required, by year, to support the end customer's product life span. For example:
 - o 2016: xx units
 - o 2017: xx units
 - o 2018: etc., for as many years as feasible

Important Dates

- May 31, 2016: Deadline for Sales to inform the Honeywell regional product manager of the customer's preferred transition option.
- August 31, 2016: Deadline for existing customers to place Last Time Buy orders; requested delivery must be by December 31, 2017.
- August 31, 2016: Affected listings will be removed from sensing.honeywell.com.
- August 31, 2016: Affected listings will be removed from technical documentation.
- August 31, 2016: Pricing will be removed from SAP so the products will not be ordered
 unknowingly by new customers. This will not affect the ability for existing customers to place
 orders during the last time buy period.

Additional Materials

Access the Rep/AD Portal for the following:

- A letter that you can modify and send to the customer
- Affected part number list
- Last Time Buy Customer's Product Forecast spreadsheet

Contact Information

- Global: Robert Robinson, Sr. Global Product Marketing Manager, robert.robinson4@honeywell.com
- North America: Tomoko Fujiwara, Product Marketing Manager, NA and Medical, tomoko.fujiwara@honeywell.com
- North America: Ryan Gaveske, Product Marketing Manager, NA and Industrial, <u>ryan.gaveske@honeywell.com</u>
- EMEA: Bryan Hovey, Product Marketing Manager, bryan.hovey@honeywell.com
- APAC: S. Sreekanth, Product Marketing Manager, <u>s.sreekanth@honeywell.com</u>
- Greater China: Ray Jin, Product Marketing Manager, ray.jin@honeywell.com

Appendix

Affected Listings and Applicable Replacements

Affected Catalog Listing	Replacement Product - Option #1	Replacement Product – Option #2
CPC0.3DFH	SSCSAAN010NDAA5	TSCSAAN001PDUCV
CPC0.3GFC	SSCSANN010NGAA5	TSCSANN001PGUCV
CPC01DFC	TSCSAAN001PDUCV	Contact HON Sales Rep or AD
CPC01DFH	TSCSAAN001PDUCV	Contact HON Sales Rep or AD
CPC01GFH	TSCSANN001PGUCV	Contact HON Sales Rep or AD
CPC01GH	TSCSNNN001PGUCV	Contact HON Sales Rep or AD
CPC05DFC	TSCSAAN005PDUCV	Contact HON Sales Rep or AD
CPC05GFC	TSCSANN005PGUCV	Contact HON Sales Rep or AD
CPC05GFH	TSCSANN005PGUCV	Contact HON Sales Rep or AD
CPC05GH	TSCSNNN005PGUCV	Contact HON Sales Rep or AD
CPC100AFC	SSCSANN100PAAA5	Contact HON Sales Rep or AD
CPC150DFC	TSCSAAN150PDUCV	Contact HON Sales Rep or AD
CPC150GFC	TSCSANN150PGUCV	Contact HON Sales Rep or AD
CPC150GH	TSCSNNN150PGUCV	Contact HON Sales Rep or AD
CPC15AC	SSCSNNN015PAAA5	Contact HON Sales Rep or AD
CPC15AFC	SSCSANN015PAAA5	Contact HON Sales Rep or AD
CPC15AFH	SSCSANN015PAAA5	Contact HON Sales Rep or AD
CPC15AH	SSCSNNN015PAAA5	Contact HON Sales Rep or AD
CPC15DFC	TSCSAAN015PDUCV	Contact HON Sales Rep or AD
CPC15GFC	TSCSANN010PGUCV	Contact HON Sales Rep or AD
CPC30AFH	SSCSANN030PAAA5	Contact HON Sales Rep or AD
CPC30AH	SSCSNNN030PAAA5	Contact HON Sales Rep or AD
CPC60DFC	TSCSAAN060PDUCV	Contact HON Sales Rep or AD
CPC60GFC	TSCSANN060PGUCV	Contact HON Sales Rep or AD
CPC60GH	TSCSNNN060PGUCV	Contact HON Sales Rep or AD
CPCL04DFC	SSCSAAN004NDAA5	NSCSAAN004NDUNV
CPCL04GC	SSCSNNN004NGAA5	NSCSNNN004NGUNV
CPCL04GFC	SSCSANN004NGAA5	NSCSANN004NGUNV

CPCL10DFC	SSCSAAN010NDAA5	TSCSAAN001PDUCV
CPCL10GFC	SSCSANN010NGAA5	TSCSANN001PGUCV
CPCL10GFH	SSCSANN010NGAA5	TSCSANN001PGUCV
CPCL10GH	SSCSNNN010NGAA5	TSCSNNN001PGUCV
CPXL04DF	NSCSANN004NDUNV	Contact HON Sales Rep or AD
CPXL04GF	NSCSANN004NGUNV	Contact HON Sales Rep or AD
CPXL10DF	NSCSAAN010NDUNV	Contact HON Sales Rep or AD
CPXL10GF	NSCSANN010NGUNV	Contact HON Sales Rep or AD
DCXL01DS	SSCSNBN001NDAA5	NSCSNBN001NDUNV
DCXL05DS	SSCSNBN005NDAA5	NSCSNBN005NDUNV
DCXL10DS	SSCSNBN010NDAA5	TSCSNBN001PDUCV
DCXL20DS	SSCSNBN020NDAA5	TSCSNBN001PDUCV
DCXL30DS	SSCSNBN030NDAA5	TSCSNBN001PDUCV
DUXL01D	NSCSDRN001NDUNV	Contact HON Sales Rep or AD
DUXL05D	NSCSDRN005NDUNV	Contact HON Sales Rep or AD
DUXL10D	NSCSDRN010NDUNV	Contact HON Sales Rep or AD
DUXL20D	NSCSDRN020NDUNV	Contact HON Sales Rep or AD
DUXL30D	NSCSDRN030NDUNV	Contact HON Sales Rep or AD
SCDA121 CPCL04GFC	SSCSANN004NGAA5	NSCSANN004NGUNV
SCDA121 CPCL04GFC	SSCSANN004NGAA5	NSCSANN004NGUNV
SCDA130 XSC100DH	TSCSSNN100PDUCV	Contact HON Sales Rep or AD
SCDA133 CPXL10DF	NSCSAAN010NDUNV	Contact HON Sales Rep or AD
SCDA144 DCXL05DS	SSCSNBN005NDAA5	NSCSNBN005NDUNV
XCX00.3DNC	SCXL010DN	Contact HON Sales Rep or AD
XCX01DNC	SCX01DN	Contact HON Sales Rep or AD
XCX01DNH	SCX01DN	Contact HON Sales Rep or AD
XCX05DNC	SCX05DN	Contact HON Sales Rep or AD
XCX05DNH	SCX05DN	Contact HON Sales Rep or AD
XCX150DNC	SCX150AN	Contact HON Sales Rep or AD
XCX15ANC	SCX15AN	Contact HON Sales Rep or AD
XCX15ANH	SCX15AN	Contact HON Sales Rep or AD
XCX15DNC	SCX15DN	Contact HON Sales Rep or AD
XCX15DNH	SCX15DN	Contact HON Sales Rep or AD
XCX30DNC	SCX30DN	Contact HON Sales Rep or AD
XCX30DNH	SCX30DN	Contact HON Sales Rep or AD
XCX60DNH	SCX100DN	SCX30DN
XCXL004DNC	SCXL004DN	Contact HON Sales Rep or AD
XCXL010DNC	SCXL010DN	Contact HON Sales Rep or AD
XPC0.3DTC	SSCSHHN010NDAA5	TSCSHHN001PDUCV
XPC01DTC	TSCSHHN001PDUCV	Contact HON Sales Rep or AD
XPC01DTH	TSCSHHN001PDUCV	Contact HON Sales Rep or AD

XPC01GTH	TSCSHNN001PGUCV	Contact HON Sales Rep or AD
XPC05DTC	TSCSHHN005PDUCV	Contact HON Sales Rep or AD
XPC05DTH	TSCSHHN005PDUCV	Contact HON Sales Rep or AD
XPC05GTH	TSCSHNN005PGUCV	Contact HON Sales Rep or AD
XPC100DC	TSCSMNN100PDUCV	Contact HON Sales Rep or AD
XPC100GFH	TSCSFNN100PGUCV	Contact HON Sales Rep or AD
XPC100GTC	TSCSHNN100PGUCV	Contact HON Sales Rep or AD
XPC150GTC	TSCSHNN150PGUCV	Contact HON Sales Rep or AD
XPC150GTH	TSCSHNN150PGUCV	Contact HON Sales Rep or AD
XPC15AFH	SSCSFNN015PAAA5	Contact HON Sales Rep or AD
XPC15ATC	SSCSHNN015PAAA5	Contact HON Sales Rep or AD
XPC15ATH	SSCSHNN015PAAA5	Contact HON Sales Rep or AD
XPC15DC	TSCSMNN015PDUCV	Contact HON Sales Rep or AD
XPC15DH	TSCSMNN015PDUCV	Contact HON Sales Rep or AD
XPC30ATC	SSCSHNN030PAAA5	Contact HON Sales Rep or AD
XPC30GTC	TSCSHNN030PGUCV	Contact HON Sales Rep or AD
XPC60DTH	TSCSHHN060PDUCV	Contact HON Sales Rep or AD
XPCL04DC	SSCSMNN004NDAA5	NSCSMNN004NDUNV
XPCL04DFC	SSCSFNN004NDAA5	NSCSHNN004NDUNV
XPCL04DTC	SSCSHHN004NDAA5	NSCSHHN004NDUNV
XPCL10DTC	SSCSHHN010NDAA5	TSCSHHN001PDUCV
XPCL10DTH	SSCSHHN010NDAA5	TSCSHHN001PDUCV
XSC01DH	TSCSSNN001PDUCV	Contact HON Sales Rep or AD
XSCL10DC	SSCSSNN010NDAA5	TSCSSNN001PDUCV
XZ204641 DCAL401GS	SSCSNBN001NDAA5	NSCSNBN001NDUNV
XZ207187XCX XCX00.3DNH	SCXL010DN	Contact HON Sales Rep or AD
XZ207188XCX XCX01DNH	SCX01DN	Contact HON Sales Rep or AD
XZ207190XCX XCX15ANH	SCX15AN	Contact HON Sales Rep or AD
XZ207191XCX XCX15DNH	SCX15DN	Contact HON Sales Rep or AD
XZ207193XCX XCX100DNH	SCX100DN	Contact HON Sales Rep or AD