

# **Customer Information Notification**

202101002I : Label and Marking RHF Change to H (Halogen free) for TDF8530, TDF8597, TDF8541/44/46/46A/46B and TDF8599/A/B/C

Note: This notice is NXP Company Proprietary.

Issue Date: Jan 08, 2021 Effective date: Jan 09, 2021

Here is your personalized notification about a NXP general announcement.

For detailed information we invite you to view this notification online

## **Management summary**

To advise all customers that product marking and packing label of certain HSOP and DBS products will be updated to reflect halogen free RHF-2006 status.

Old RHF-2006 status: E New RHF-2006 status: H

### **Change Category**

[]Wafer Fab Process	[]Assembly Process	[X]Product Marking	[]Test Process	[]Design
[]Wafer Fab Materials	[]Assembly Materials	[]Mechanical Specification	[]Test Equipment	[]Errata
[]Wafer Fab Location	[]Assembly Location	[X]Packing/Shipping/Labeling	[]Test Location	[]Electrical spec./Test coverage
c 3	F 3 O 41			

[]Firmware []Other

# **PCN** Overview

# **Description**

The following changes are applied:

- 1. Change of product marking line C
- 2. Change of product packing label PMC (Product Marking Code) 3 digit code

#### Reason

To reflect halogen free RHF-2006 code in both product marking and product packing label.

#### **Identification of Affected Products**

Packing Labels

Last digit of PMC code (Product Manufacturing Code) and product making will change too, E to H. example: T-S-E will change to T-S-H

The following changes are applied:

- 1. Change of product marking line C, T-S-E will change to T-S-H
- 2. Change of product packing label PMC (Product Marking Code) 3 digit code T-S-E will change to T-S-H

# Anticipated Impact on Form, Fit, Function, Reliability or Quality

No Impact on form, fit, function, reliability or quality **Data Sheet Revision**No impact to existing datasheet **Disposition of Old Products**Existing inventory will be shipped until depleted

## Remarks

New label and marking shows product is environmental friendly, halogen free.

# **Contact and Support**

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

### **About NXP Semiconductors**

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

**NXP Semiconductors** 

High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006- 2021 NXP Semiconductors. All rights reserved.

### Affected OPN

TDF8599CTH/N1,112

TDF8599CTH/N1,118

TDF8597TH/N1,118

TDF8544SD/N3,112

TDF8530TH/N2,112

TDF8530TH/N2,118

TDF8541JS/N3,512

TDF8541JS/N3MP

TDF8541J/N3,112

TDF8541SD/N3,112

TDF8541TH/N3,118

TDF8544J/N3,112

TDF8544TH/N3,118

TDF8546J/N2,112

TDF8546JS/N2,512

TDF8546TH/N2,118

TDF8546ATH/N1,118

TDF8546ASD/N1,112

TDF8546AJS/N1,512

TDF8546AJ/N1,112

TDF8546AJ/N1ZU

TDF8546AJS/N1ZS

TDF8546AJS/N1ZMP

TDF8546ASD/N1ZU

TDF8546ATH/N1ZJ

TDF8546J/N2ZU

TDF8546JS/N2ZS

TDF8546JS/N2ZMP

TDF8546TH/N2ZJ

TDF8599ATH/N2CS

TDF8599ATH/N2CY

TDF8599BTH/N1CS

TDF8599BTH/N1CY

TDF8546BTH/N1J

TDF8546BTH/N1ZJ