

P.O. Box 14460  
St. Louis, MO 63178-4460  
114 Old State Road  
Ellisville, MO 63021  
Phone: (636) 527-3877

Date: **April 03, 2007**  
To: PC04F / PC06F fuse customers  
Subject: **PC04F / PC06F Fuse END of LIFE NOTICE**

Cooper Bussmann is discontinuing the PC04F and PC06F fuse Series.

The recommended replacement for the PC06F is the RoHS compliant 0603FA-R Series CHIP™ Fuse.

The 0603FA-R Series is immediately available and its data sheet is on our website  
([www.cooperbussmann.com](http://www.cooperbussmann.com)).

---