	DT
--	----

Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

	FRODUCT DISCU	DIVINUANCE NOTICE (FD)	
PDN #:	SG-12-01	Last Buy Deadline for Submission of Order:	30-Mar-2013
Issue Date:	30-Mar-2012	Last Eligible Ship Date:	30-Jun-2013
Contact: Title:	Libbie Nicholson-Kramer Sr. Tactical Marketing Manager		
Phone #: Fax #: E-mail:	512-330-3140 512-330-3105		
PRODUCT(libbie.nicholson-kramer@idt.com S) AFFECTED: ent Part #(s), if any)	ATTACHMENT Yes	🗆 No
-	Audio parts as listed in Attachment I wil	l be discontinued.	
REASON FO	OR DISCONTINUANCE:		
□ Obsolete F	ower speed with faster speed offerings Fab Technology / Process	□ Other:	
	Assembly Technology / Process		
□ Obsolete F	Package / Material		
Declined N	Market		
As a result of through this l converting to Last time bu	Product Discontinuance Notice (PDN). V equivalent devices offered. Please use a	DT has decided to discontinue certain products and Ve recommend you to check detailed specifications acknowledgement below or E-Mail to request addit r to the date indicated above. All orders shall be su by IDT in writing.	before tional information.
-	-	ntact your local IDT distributor or sales rep	resentative.
Customer:		E-Mail Address:	
Name/Date:		Phone#:	
Title:		Fax# :	
CUSTOME	R COMMENTS:		
IDT ACKN	OWLEDGEMENT:		
Received By:		Date:	



Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: SG-12-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
92HD71B5X3NLGXB3X	None	STAC9202X3TAEA1XR	None
92HD71B5X3NLGXB3X8	None	STAC9202X5TAEA1X	None
92HD71B5X3PRGXB3X	None	STAC9202X5TAEA1XR	None
92HD71B5X3PRGXB3X8	None	STAC9204X3NBEB2X	None
92HD71B5X5NLGXB3X	None	STAC9204X3NBEB2XR	None
92HD71B5X5NLGXB3X8	None	STAC9204X3TAEB2X	None
92HD71B5X5PRGXB3X	None	STAC9204X3TAEB2XR	None
92HD71B5X5PRGXB3X8	None	STAC9204X5NBEB2X	None
92HD71B7A5NLGXB3X	None	STAC9204X5NBEB2XR	None
92HD71B7A5NLGXB3X8	None	STAC9204X5TAEB2X	None
92HD71B7X3NLGXB3X	None	STAC9204X5TAEB2XR	None
92HD71B7X3NLGXB3X8	None	STAC9205X3NBEB2X	None
92HD71B7X3PRGXB3X	None	STAC9205X3NBEB2XR	None
92HD71B7X3PRGXB3X8	None	STAC9205X3TAEB2X	None
92HD71B7X5NLGXB3X	None	STAC9205X3TAEB2XR	None
92HD71B7X5NLGXB3X8	None	STAC9205X5NBEB2X	None
92HD71B7X5PRGXB3X	None	STAC9205X5NBEB2XR	None
92HD71B7X5PRGXB3X8	None	STAC9205X5TAEB2X	None
92HD71B8X3NLGXB3X	None	STAC9205X5TAEB2XR	None
92HD71B8X3NLGXB3X8	None	STAC9250G3TAEA1X	None
92HD71B8X3PRGXB3X	None	STAC9250G3TAEA1XR	None
92HD71B8X3PRGXB3X8	None	STAC9250G5TAEA1X	None
92HD71B8X5NLGXB3X	None	STAC9250G5TAEA1XR	None
92HD71B8X5NLGXB3X8	None	STAC9251G3TAEA1X	None
92HD71B8X5PRGXB3X	None	STAC9251G3TAEA1XR	None
92HD71B8X5PRGXB3X8	None	STAC9251G5TAEA1X	None
92HP61B7X5NLGXB3X	None	STAC9251G5TAEA1XR	None
92HP61B7X5NLGXB3X8	None	STAC9752AXNAED1X	None
92HP61B7X5PRGXB3X	None	STAC9752AXNAED1XR	None
92HP61B7X5PRGXB3X8	None	STAC9753AXNAED1X	None
STAC9202X3TAEA1X	None	STAC9753AXNAED1XR	None