Product Change Notification - SYST-17PPWV791

Date:	18 Apr 2017
Product Category:	Ethernet Controllers
Affected CPNs:	
Notification subject:	Data Sheet - LAN9221/LAN9221i High-Performance 16-bit Non-PCI 10/100 Ethernet Controller
	with Variable Voltage I/O
Notification text:	SYST-17PPWV791
	Microchip has released a new DeviceDoc for the LAN9221/LAN9221i High-Performance 16-bit Non-PCI 10/100 Ethernet Controller wit of devices. If you are using one of these devices please read the document located at LAN9221/LAN9221i High- Performance 16-bit Non-PCI 10/100 Ethernet Controller wit.
	Notification Status: Final
	Description of Change: 1) Replaces previous SMSC version Rev. 2.9 2) Changed from: "After any PHY reset, the application must wait until the "Link Status" bit in the PHY's "Basic Status Register" (PHY Reg. 1.2) is set before attempting to transmit or receive data." To: "After any PHY reset, the application should wait until the "Link Status" bit in the PHY's "Basic Status Register" (PHY Reg. 1.2) is set before attempting to transmit data, otherwise data written to the TX FIFO will only be sent when the Link Status returns to "Up"."
	Impacts to Data Sheet: None
	Reason for Change: To Improve Manufacturability
	Change Implementation Status: Complete
	Date Document Changes Effective: 18 April 2017
	NOTE: Please be advised that this is a change to the document only the product has not been changed.
	Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s): LAN9221/LAN9221i High-Performance 16-bit Non-PCI 10/100 Ethernet Controller wit

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at http://www.microchip.com/PCN sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to microchipDIRECT and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

 $SYST-17PPWV791 - Data Sheet - LAN9221/LAN9221i \ High-Performance \ 16-bit \ Non-PCI \ 10/100 \ Ethernet \ Controller \ with Variable \ Voltage \ I/O$

Affected Catalog Part Numbers (CPN)

LAN9221I-ABZJ LAN9221-ABZJ