

PDN# 20180521002D End of Life for DLP® Pico VSP DMD's Product Discontinuance Notification RevD accelerated Pico VSP DMD EOL dates

Date: January 31, 2019 To: Digi-Key PCN

Dear Customer:

The recipient has been identified for notification of changes for one or more of the products affected by the change detailed in the notice. Customers are notified based on the past twenty-four (24) months of the customer's purchase history or the recipient is listed as being part of GIDEP (Government-Industry Data Exchange Program).

Please note that the notification period has been accelerated compared to TI's standard process. Due to 2019 supply and capacity limitations, TI has pulled-in most of the Pico VSP DMD last order date to *March-15-2019* and last ship dates to *September-30-2019* (Reference table 1 below).

Last order and last ship dates in this PDN 20180521002D notification supersede dates in previous revisions.

In an attempt to satisfy continuing requirements, TI is offering a non-cancelable, nonrefundable lifetime buy for the product. Related dates are included in the notification. We will contact you as soon as we have completed a review of all customer responses and determined the appropriate course of action required to satisfy the need for this/these products.

If additional supply is required beyond the dates defined in this letter, please contact your local Field Sales Representative to determine if the parts may be available from a TI-authorized distributor for discontinued products. There is no guarantee of continued supply for these products.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (<u>PCN_ww_admin_team@list.ti.com</u>).

Sincerely,

PCN Team SC Business Services

Attachments1

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE

CUSTOMER PART NUMBER

DLP2000FQC DLP4500FQE DLP4501FQG null null null

Det	ails of	this Product	: Disc	ontinuance follow on th	ie next page(s).			
PDN Number: 20180			0521	521002 <mark>D</mark>			ate: 1/31/2019		
Title:	Discontinuance of DLP® Pico VSP devices								Ī
Customer Contact:				PCN-Team@list.ti.com		Dept:	Quality Services		
Last date to order:			See	e Table 1	Last date t	o ship:	See Table 1		
Change T	ype:		Pr	Product Discontinuance - End Of Life					
		Pro	duc	t Discontinuance	Notificatio	on Deta	ils		
Descripti	on of I	Discontinu	ance	:					
changing of buy is bein device par cancelable for availab NOTE: Th	of a pro ng offer rt numt e and ne bility. nere are	oprietary ma red as per th pers are pro on-refundat e no sample	ateria he La vided ble, an s offe	TI) is announcing the of I used in the DMD proc st Date to Order and La I in the Product Affected nd subject to availabilit ered for withdrawn/obso al sales representative.	ess. A non-c ast Date to S d section belo y. Please con	ancelable, nip indicat w. Orders tact your	, non-re ed abov s will be local sa	fundable lifetime /e. Replacement considered non- les representative	
Reason fo	or Disc	continuanc	e '						
				e chemical use policy a	and continuat	ion of sup	ply		_
Product A	Affecte	<mark>ed; accele</mark> ra	ated	EOL dates					
				TABLE	1				
DMD		Orderable P	/N	New Material or recomme	nd Revised I	.ast Order D	ate	Revised Last Ship Da	ite
.45WXGA S31	11	1191-403B	F	DLP4501AFQG	3/	<mark>15/2019</mark>		<mark>9/30/2019</mark>	
.45 W/(d/(05)		DLP4501FQ	G		3/	<mark>15/2019</mark>		<mark>9/30/2019</mark>	
.45WXGA S24	41	1191-403B	Т	1191-413BT	3/	<mark>15/2019</mark>		<mark>9/30/2019</mark>	
.45 W/(G/(52-	11	DLP4500FQ	E	DLP4500AFQE	3/	<mark>3/15/2019</mark>		<mark>9/30/2019</mark>	
.45WXGA S31	10	1191-403B	С	1191-413BC	3/	<mark>3/15/2019</mark>		<mark>9/30/2019</mark>	
		DLP4500FQ	D	DLP4500AFQD	3/	<mark>3/15/2019</mark>		<mark>9/30/2019</mark>	
45WXGANIR S	310	DLP4500NIRF	QD	DLP4500NIRAFQD	3/	<mark>15/2019</mark>		<mark>9/30/2019</mark>	
	510	1191N403R	C			Closed		6/27/2019	
.30WVGA-S220		6860-303BI	D			Closed		6/24/2019	
	20	6860-303A	т	Replace w/ DLP3010AFQ	K	Closed		6/24/2019	
	20	6860-313AT				Closed		6/24/2019	
		DLP3000FQ	В			Closed		6/24/2019	
WVGA-S242 (242 (EM) 6860-303BG Replace w/ DLP2010A		Replace w/ DLP2010AFC	J 1/	31/2019	12/31/2019			
	244	DLP4500NIRF	QE			Closed		6/27/2019	
15WXGANIR-S	241	1191N403R		Replace w/ DLP4500NIRAF	QD	Closed		6/27/2019	
.17HVGA-S21	10	DLP1700FQ	A	Replace W/DLP2000AFQ	C	Closed		6/24/2019	

.2nHD S230	3664-203BT			7/1/2019		12/2/2019	
.21100 3230	DLP2000FQC	DLP2000AFQ	7/1/2019			12/2/2019	
Product Affected;							
DMD	Orderable P/N	New Orderable P/N	Replacement Code		DMD Samples	Sample Order PN	
	1191-403BF				Available	DLP4501AFQG	
.45WXGA \$311	DLP4501FQG	DLP4501AFQG	Q (requires software update)**				
	1191-403BC	1191-413BC	Q (requires software update)**			1191-413BC	
.45WXGA \$310	DLP4500FQD	DLP4500AFQD			Available	DLP4500AFQD	
	1191-403BT	1191-413BT	Q (requires software update)**		A	1191-413BT	
.45WXGA S241	DLP4500FQE	DLP4500AFQE			Available	DLP4500AFQE	
	DLP4500NIRFQD	DLP4500NIRAFQD	Q (requires software update)*			DLP4500NIRAFQD	
.45WXGANIR S31	.0 1191N403RC	DLP4500NIRAFQD			Available		
.2 nHD	3664-203BT	DLP2000AFQC	Q (requires software update)*		Mar-19	XDLP2000AFQC	
.2 1100	DLP2000FQC	DLP2000AFQC					
.45WXGANIR-S24	DLP4500NIRFQE	DLP4500NIRAFQD	F (Similar functionality but not equivalent)		Available	DLP4500NIRAFQD	
.45WXGANIK-524	1191N403RT	DLP4500NIRAFQD					
	6860-303BD		F (Similar functionality but not equivalent)		Available	DLP3010AFQK	
.30WVGA-S220	6860-303AT	DLP3010AFQK					
.5000000-5220	6860-313BT	DLPSUIUAFQK					
	DLP3000FQB						
.3 WVGA-S242 (EI	M) 6860-303BG	6860-303BG DLP2010AFQJ F (Similar functionality but not equivalent)		Available	DLP2010AFQJ		
.24VGA-S240	24VGA-S240 6845-203BD DLP2000AFQC F (Similar functionality built of equivalent)		•	Mar-19	XDLP2000AFQC		
.17HVGA-S210	DLP1700FQA	DLP2000AFQC	F (Simila	r functionality but not equivalent)	Mar-19	XDLP2000AFQC	

*The latest version of firmware can be found at http://www.ti.com/tool/dlpr350

**Detailed information will be found in the following Application Note found on the DLP[®] extranet: <u>Software Requirements for TI DLP® Pico™ VSP Digital Micromirror Devices.</u> If your controller software comes pre-loaded with the optical engine you purchase, or if your controller software is provided by a third party, please verify the appropriate software version with the provider.

Replacement Notes:

- F = Similar functionality but not equivalent.
- P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.
- Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.
- S = EXACT equivalent in functionality and parametrically to the compared device.

DMD GPN	DMD Description	Controller GPN	Controller Orderable PN	Required System Software Version	SW Availability
DLP4501	.45 WXGA S241, S310, S311	DLPC6401	DLPC6401ZFF	Version 7.0.0 or higher	Available
DLP4500	.45 WXGA S241, S310	DLPC350	DLPC350ZFF	DLPR350PROM_V4.0.2	Available
DLP4500NIR	.45 WXGA NIR	DLPC350	DLPC350ZFF	DLPR350PROM_V4.0.2	Available
DLP2000	.2 nHD	DLPC2607	DLPC2607ZVB	Available at Validation	April-2019

DMD / Controller / Software Information

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or contact your local Field Sales Representative.

Location	E-Mail
DLP [®] Products	<u>Dlp-pcn-team@list.ti.com</u>
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com