

The following is a new Micron Part Change Notification. If you have questions regarding this email, please contact your sales representative, field support team or use the information request button in this email.

EOL of Select 30nm DDR2 SDRAM Component and Modules

PCN: 32512

Published: 2017-10-18				
Туре:	End of Life			
Description:	Micron will end of life select DDR2 SDRAM component and modules			
Reason:	Better Align With Industry Standard, Change in Market Demand			
Product Affected:	Select 30nm DDR2 SDRAM component and modules listed below			
Affected Micron Part Number		Recommended Replacement	Customer Part Number	
Component				
MT47H128M4SH-25E:H		Contact Factory		
Module				
MT16HTF25664HIZ-667M1		Contact Factory		
MT4HTF6464HZ-800M1		Contact Factory		
MT8HTF12864AZ-800M1		Contact Factory	MT8HTF12864AZ-800M1- ND	
MT8HTF12864HDZ-800M1		Contact Factory		
MT8HTF25632HZ-667M1		Contact Factory		
MT9HTF12872AZ-80EM1		Contact Factory		
MT9HTF12872RHZ-80EM1		Contact Factory		
MT9HTF6472RHZ-667H1		Contact Factory		

*Materials that have been ordered are in **bold**.

Method of Identification:	Marketing Part Number
Micron Sites	All Sites

Affected:	
Last Purchase Date*:	2018-04-18
Last Shipment Date:	2018-10-18

*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Thank you

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.