

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134

PRODUCT DISCONTINUANCE NOTICE

PDN #: M000427

DATE: 07-Sep-2010

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	MAX8890ETCAAA	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8890ETCAAA-T	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8890ETCABK	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8890ETCBBB	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8890ETCBBB-T	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8890ETCDDD	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8890ETCDDD-T	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8890ETCJJJ	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8890ETCJJJ-T	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8890ETCMMM	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8890ETCMMM-T	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Discontinuance	MAX8890EAAA	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EAAA+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCAAA	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCAAA+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCAAA+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCAAA-T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCABK	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCABK+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCABK+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCABK-T	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Discontinuance	MAX8890EGCAKM	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCAKM+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCAKM+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCAKM-T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCBBB	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Oct-2010

Discontinuance	MAX8890EGCBBB+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCBBB+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCBBB-T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCBKK	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCBKK+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCBKK+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCBKK-T	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Discontinuance	MAX8890EGCDDD	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCDDD+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCDDD+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCDDD-T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCDDM	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCDDM+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCDDM+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCDDM-T	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Discontinuance	MAX8890EGCGGG	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCGGG+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCGGG+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCGGG-T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCJJJ	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCJJJ+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCJJJ+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCJJJ-T	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Discontinuance	MAX8890EGCMMM	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCMMM+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCMMM+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EGCMMM-T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EMMM	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890EMMM+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ESDAAA	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ESDMMM	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCAAA+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCAAA+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCABK+	N/A	31-Mar-2011	06-Sep-2012	The part was not released
Discontinuance	MAX8890ETCABK+T	N/A	31-Mar-2011	06-Sep-2012	The part was not released
Discontinuance	MAX8890ETCABK-T	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Oct-2010

Discontinuance	MAX8890ETCAKM	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCAKM+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCAKM+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCAKM-T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCBBB+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCBBB+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCBKK	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCBKK+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCBKK+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCBKK-T	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Discontinuance	MAX8890ETCDDD+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCDDD+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCGGG	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCGGG+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCGGG+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCGGG-T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCHHH	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCHHH+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCHHH+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCHHH-T	N/A	31-Mar-2011	06-Sep-2012	Part is leaded. Request information on lead-free version
Discontinuance	MAX8890ETCJJJ+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCJJJ+T	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCMMM+	N/A	31-Mar-2011	06-Sep-2012	Part can no longer be manufactured
Discontinuance	MAX8890ETCMMM+T	N/A	31-Mar-2011	06-Sep-2012	The part was not released