PCN Number:		201	710120	າດດ		PCN Date:	October 13, 2017					
			20171012000 r TXS0102-Q1				1 Cit Bater	october 13, 2017			, 2017	
			PCN Manager						Dept:		Quality Services	
Change Type:												
Assembly Site				Design				Wafe	r Bump Site			
Assembly Process				\boxtimes	_ Data officer					r Bump Material		
Assembly Materials			Щ	Part number change			<u>Ц</u>		r Bump Process			
Mechanical Specification			ᆜ	Test Site			<u> </u>		r Fab Site			
Packing/Shipping/La			Labell	aing _ res		Test Proce	est Process		H		r Fab Materials	
Notification Details Wafer Fab Process									I Tab Flocess			
Description of Change:												
Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.												
TEXAS INSTRUMENTS SCES854A - MAY 2014 - REVISED SEPTEMBER 2								TXS0102-Q1				
Changes from Original (May 2014) to Revision A Page												
Changed Handling Ratings table to ESD Ratings table												
Changed Functional Block Diagram with new figure												
	Changed TXS0102-Q1 Layout Example with new figure											
Added Documentation Support, Receiving Notification of Documentation Updates and Community Resources												
The state of the s												
The datasheet number will be changing.												
Device Family						Change	Change From:			Change To:		
TXS0102-Q1				SCES854			SCES854A					
These changes may be reviewed at the datasheet links provided.												
http://www.ti.com/product/TXS0102-Q1												
Reason for Change:												
To reflect the device pin descriptions and the interconnections in the figure accurately.												
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):												
No anticipated impact. This is a specification change announcement only. There are no changes												
	to the actual device. Changes to product identification resulting from this PCN:											
		s to product	identi	ificatio	on r	esulting f	rom this PCI	N:				
Noi												
		Affected:										
$ \mid T \rangle$	(S010	2QDCURQ1										

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com