


# BOURNS®

## Product Update Memo

### CHIP RESISTORS



Revised April 12, 2016

## Change to Minimum Order Quantity for Various Chip Resistors

Bourns is adjusting the Minimum Order Quantity (MOQ) for various chip resistors listed below effective April 3, 2016. A list of the affected part numbers is shown in the attached excel file.

Model	Current MOQ	New MOQ
CRO402-F 1% (-GLF)	10,000	20,000
CRO402-J 5% (-GLF)	10,000	20,000
CRL0603-F 1% (-ELF)		
-R470 to -R910	5,000	10,000
-1R00 to -9R10	5,000	20,000
CRL0603-J 5% (-ELF)		
-R470 to -R910	5,000	10,000
-1R00 to -9R10	5,000	50,000
CRL0805-F 1% (-ELF)		
-R620 to -R910	5,000	10,000
-1R00 to -9R10	5,000	10,000
CRL0805-J 5% (-ELF)		
-R100 to -R560	5,000	10,000
R620 to -R910	5,000	10,000
-1R00 to -9R10	5,000	30,000

Model	Current MOQ	New MOQ
CRL1206-F 1% (-ELF)		
-R620 to -R910	5,000	10,000
-1R00 to 9R10	5,000	10,000
CRL1206-J 5% (-ELF)		
-R620 to -R910	5,000	10,000
-1R00 to 9R10	5,000	20,000
CAY16-...J2 5% (LF)	5,000	10,000
CAY16-...J4 5% (LF)	5,000	10,000
CRT0402-FZ-xxxxGLF	10,000	20,000
CRT0603-DY-xxxxELF	5,000	10,000
CRT0603-DZ-xxxxELF	5,000	10,000
CRT0603-FY-xxxxELF	5,000	10,000
CRT0603-FZ-xxxxELF	5,000	10,000
CRT0805-FY-xxxxELF	5,000	10,000
CRT0805-FZ-xxxxELF	5,000	10,000
CRT1206-FZ-xxxxELF	5,000	10,000

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).