

Micron 1300 End of Life

PCN: 33859

Published: 2020-12-08

Туре:	End of Life			
Description:	Micron 1300 solid state client drives will be ending production.			
Reason:	Better Align With Industry Standard			
Product Affected:	All 1300 products			
Affected Micron Part Number		Recommended Replacement	Customer Part Number	
<u>Module</u>				
MTFDDAK1T0TDL-1AW12AB	YY			
MTFDDAK1T0TDL-1AW1ZAB	YY			
MTFDDAK256TDL-1AW12ABYY				
MTFDDAK256TDL-1AW1ZABYY		MTFDDAK256TDL-1AV	/1ZABYY-ND	
MTFDDAK2T0TDL-1AW12AB	YY			
MTFDDAK2T0TDL-1AW1ZABYY				
MTFDDAK512TDL-1AW12AB	YY			
MTFDDAK512TDL-1AW1ZAB	YY			
MTFDDAV1T0TDL-1AW12ABY	YY			
MTFDDAV1T0TDL-1AW1ZAB	YY			
MTFDDAV256TDL-1AW12ABYY				
MTFDDAV256TDL-1AW1ZABYY				
MTFDDAV512TDL-1AW12ABYY				
MTFDDAV512TDL-1AW1ZABY	YY			
		*Materials that have been ordered are in bol	ld.	
Method of Identification:	1300 Micron SSI	O label		
Micron Sites Affected:	All Sites			
Last Purchase Date*:	2021-06-30			
Last Shipment Date:	2021-12-30			

Early placement of orders is encouraged as an increase in demand for this product could potentially exceed Micron's ability to meet all requests. All products from a previously accepted order that have not shipped as of the last-time purchase date will be considered non-cancelable and non-returnable. Changes to confirmed request dates will also require written approval by Micron. Should additional supply be available after the last-time purchase date, Micron may accept orders for product and such orders placed will be considered non-cancelable and non-returnable.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Attachments

There are no attachments on this PCN