



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001041

DATE: 03-Sep-2021

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX619C/D+C0N	N/A	02-Dec-2021	04-Mar-2023	Part can no longer be manufactured
Discontinuance	VT1677SBFQ	N/A	02-Dec-2021	04-Mar-2023	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 04-Oct-2021