

Product Change Notification - SYST-05PREF081

Date:

06 Aug 2019

Product Category:

Clock and Timing - Clock and Data Distribution

Affected CPNs:

7 🔁

Notification subject:

Data Sheet - SY100EL11V 5V/3.3V ECL 1:2 Differential Fanout Buffer

Notification text:

SYST-05PREF081 Microchip has released a new DeviceDoc for the SY100EL11V 5V/3.3V ECL 1:2 Differential Fanout Buffer of devices. If you are using one of these devices please read the document located at <u>SY100EL11V 5V/3.3V ECL 1:2 Differential Fanout Buffer</u>.

Notification Status: Final

Description of Change:

1) Updated minimum values for Common Mode Range voltage in PECL DC Electrical Characteristics table and NECL DC Electrical Characteristics table.

2) Updated two Conditions values for tSKEW in AC Electrical Characteristics table.

3) Minor stylistic updates to align data sheet with current style.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 06 Aug 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

SY100EL11V 5V/3.3V ECL 1:2 Differential Fanout Buffer

Please contact your local <u>Microchip sales office</u> with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our <u>PCN home page</u> select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the <u>PCN FAQ</u> section.

If you wish to <u>change your PCN profile</u>, <u>including opt out</u>, please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

SY100EL11VZG SY100EL11VZG-TR