

<b>PDN Number:</b>	20181002000.3		<b>PDN Date:</b>	Oct 3, 2018
<b>Title:</b>	Discontinuance of Select TLCxxxx devices			
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>		<b>Dept:</b>	Quality Services
<b>Last date to order:</b>	Oct 3, 2019	<b>Last date to ship:</b>	Apr 3, 2020	
<b>Change Type:</b>	Product Discontinuance - End Of Life			
<b>Product Discontinuance Notification Details</b>				
<b>Description of Discontinuance:</b>				
Texas Instruments, Incorporated (TI) is announcing the discontinuance of select TLCxxx devices. A life time buy is being offered per the date shown above. Recommended replacements are being offered as shown in the Product Affected Section.				
NOTE: There are no samples offered for withdrawn/obsolete products. For samples of any replacement products, please contact your local sales representative.				
<b>Reason for Withdrawal/Discontinuance:</b>				
Potential continued reliable product support is at risk due to an unsupported tool set which could not be offloaded.				
<b>Product Affected:</b>				
	<b>DEVICES BEING DISCONTINUED</b>	<b>RECOMMENDED REPLACEMENT PRODUCTS</b>	<b>REPLACEMENT CODES</b>	
	TLC1541CDW	ADS7956SDBT	F	
	TLC1541CFN	ADS7956SRHBT	F	
	TLC1541CN	ADS7956SDBT	F	
	TLC1541IDW	ADS7956SDBT	F	
	TLC1541IDWR	ADS7956SDBTR	F	
	TLC1541IFN	ADS7956SRHBT	F	
	TLC1541IFNG3	ADS7956SRHBT	F	
	TLC1541IN	ADS7956SDBT	F	
	TLC540IDW	ADS7960SDBT	F	
	TLC540IDWR	ADS7960SDBTR	F	
	TLC540IFN	ADS7960SRHBT	F	
	TLC540IFNG3	ADS7960SRHBT	F	
	TLC540IFNR	ADS7960SRHBR	F	
	TLC540IN	ADS7960SDBT	F	
	TLC541IDW	ADS7960SDBT	F	
	TLC541IDWR	ADS7960SDBTR	F	
	TLC541IFN	ADS7960SRHBT	F	
	TLC541IFNR	ADS7960SRHBR	F	
	TLC541IN	ADS7960SDBT	F	
	TLC542CDW	ADS7960SDBT	F	
	TLC542CDWG4	ADS7960SDBT	F	
	TLC542CDWR	ADS7960SDBTR	F	
	TLC542CN	ADS7960SDBT	F	
	TLC542CNE4	ADS7960SDBT	F	

TLC542IDW	ADS7960SDBT	F
TLC542IDWG4	ADS7960SDBT	F
TLC542IDWR	ADS7960SDBTR	F
TLC542IFN	ADS7960SRHBT	F
TLC542IFNR	ADS7960SRHBR	F
TLC542IFNRG3	ADS7960SRHBR	F
TLC542IN	ADS7960SDBT	F
TLC545CFN	ADS7961SRHBT	F
TLC545IFN	ADS7961SRHBT	F
TLC548CD	ADC081S021CIMF/NOPB	F
TLC548CDR	ADC081S021CIMFX/NOPB	F
TLC548CP	ADC081S021CIMF/NOPB	F
TLC548ID	ADC081S021CIMF/NOPB	F
TLC548IDR	ADC081S021CIMFX/NOPB	F
TLC548IP	ADC081S021CIMF/NOPB	F
TLC549CD	ADC081S021CIMF/NOPB	F
TLC549CDG4	ADC081S021CIMF/NOPB	F
TLC549CDR	ADC081S021CIMFX/NOPB	F
TLC549CDRG4	ADC081S021CIMFX/NOPB	F
TLC549CP	ADC081S021CIMF/NOPB	F
TLC549ID	ADC081S021CIMF/NOPB	F
TLC549IDG4	ADC081S021CIMF/NOPB	F
TLC549IDR	ADC081S021CIMFX/NOPB	F
TLC549IDRG4	ADC081S021CIMFX/NOPB	F
TLC549IP	ADC081S021CIMF/NOPB	F
TLC549IPS	ADC081S021CIMF/NOPB	F
TLC549IPSR	ADC081S021CIMFX/NOPB	F

**Replacement Notes:**

F = Similar functionality but not equivalent.

P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.

Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.

S = EXACT equivalent in functionality and parametrically to the compared device.

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>