	Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138 Phone #: (408) 284-8200				
PRODUCT DISCONTINUANCE NOTICE (PDN)					
PDN #: <u>N-12-36</u>	Last Buy Deadline for Submission of Order:	12-Dec-2013			
Issue Date: <u>12-Dec-2012</u>	Last Eligible Ship Date:	12-Mar-2014			
Contact:IDT Clock MarketingE-mail:clocks@idt.com	Team				
PRODUCT(S) AFFECTED: ATTACHMENT Yes No (List Replacement Part #(s), if any) If any If any If any					
Selective Clock devices as listed in	Attachment I will be discontinued.				
REASON FOR DISCONTINUANCE:					
 Replace slower speed with faster s Obsolete Fab Technology / Proce Obsolete Assembly Technology / Obsolete Package / Material Declined Market 	SS				
through this Product Discontinuance converting to equivalent devices off Last time buy orders may be submit by IDT at its sole discretion unless	(s) listed above, IDT has decided to discontinue certain products a Notice (PDN). We recommend you to check detailed specificatio ered. Please use acknowledgement below or E-Mail to request add ted any time prior to the date indicated above. All orders shall be otherwise agreed by IDT in writing.	ns before ditional information. subject to acceptance			
Customer:	E-Mail Address:				
Name/Date:	Phone#:	Phone#:			
Title:	Fax# :	Fax# :			
CUSTOMER COMMENTS:					
IDT ACKNOWLEDGEMENT:					
Received By:	ed By: Date:				



Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: N-12-36

Affected Part Numbers

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
MC100ES6220AE	NONE	MC100ES6221TB	NONE
MC100ES6220AER2	NONE	MC100ES6221TBR2	NONE
MC100ES6220TB	NONE	MC100ES6222AE	87322BYILF (not ePad)
MC100ES6220TBR2	NONE	MC100ES6222AER2	87322BYILFT (not ePad)
MC100ES6221AE	NONE	MC100ES6222TB	87322BYI (not ePad)
MC100ES6221AER2	NONE	MC100ES6222TBR2	87322BYIT (not ePad)